

NGP ANNUAL COMPLIANCE REPORT - 2025

Revision Number: 1

Revision Date: 18/08/2025

INTERNAL

© Jemena Limited. All rights reserved. Copyright in the whole or every part of this document belongs to Jemena Limited, and cannot be used, transferred, copied or reproduced in whole or in part in any manner or form or in any media to any person other than with the prior written consent of Jemena.

Printed or downloaded copies of this document are deemed uncontrolled



DOCUMENT HISTORY

| Revision | Date | Author | Description of Changes |
|----------|------------|----------------|------------------------|
| 1.0 | 18/08/2025 | Rahul Dorairaj | New Document |

OWNING FUNCTIONAL GROUP & DEPARTMENT / TEAM

People, Safety & Legal : Environment and Sustainability

TABLE OF CONTENTS

| | | |
|-----|---|----|
| 1 | INTRODUCTION..... | 4 |
| 1.1 | EPBC APPROVAL KEY INFORMATION SUMMARY..... | 4 |
| 1.2 | EPBC APPROVAL CONDITIONS – COMPLIANCE STATUS..... | 4 |
| 1.3 | PLAINS DEATH ADDER HABITAT DISTURBANCE AND REMOVAL..... | 11 |
| 2 | APPENDICES | 12 |
| 2.1 | APPENDIX A – TRANSITIONAL REHABILITATION MONITORING REPORT - 2025 | 12 |
| 2.2 | APPENDIX B – NOTIFICATION OF COMMENCEMENT | 13 |

1 INTRODUCTION

Jemena Northern Gas Pipeline Pty Ltd (referred to herein as *Jemena*) gained approval under the *Environmental Protection and Biodiversity Conservation Act 1999* (Cth) (EPBC Act) in 2017 as the approval holder to construct and operate the Jemena Northern Gas Pipeline, from Tennant Creek, Northern Territory to Mt Isa, Queensland (EPBC 2015/7569). The Northern Gas Pipeline involves the construction of a new, underground, natural gas transmission pipeline, approximately 622 km in length and the associated facilities.

This Annual Compliance report will cover compliance against each of the EPBC conditions issued to Jemena between 21 May 2024 and 20 May 2025 period.

1.1 EPBC APPROVAL KEY INFORMATION SUMMARY

| | |
|--|--|
| EPBC Number | EPBC 2015/7569 |
| Project Name | Jemena Northern Gas Pipeline |
| Approval Holder and ACN | Jemena Northern Gas Pipeline Pty Ltd (ACN: 607 928 790) |
| Approved Action | Construct and Operate a buried 622 km high-pressure gas pipeline from Tennant Creek (Northern Territory) to Mount Isa (Queensland) |
| Location of the Project | Tennant Creek (Northern Territory) to Mount Isa (Queensland) |
| Project Commencement Date | 20 May 2017 |
| Person accepting responsibility of this report | Rahul Dorairaj |
| Dates for the reporting period of this report | 21 May 2024 to 20 May 2025 |

1.2 EPBC APPROVAL CONDITIONS – COMPLIANCE STATUS

A total of 15 environmental approval conditions were placed on the project. The compliance status of these 15 approval conditions is detailed below:

| Condition Number | Condition | Is the Project compliant with this condition? | Evidence/ Comments |
|------------------|---|---|---|
| 1 | The approval holder must only take the proposed action within the project area . | Compliant | <p>All operations during this period have been within the designated project area as described in the final public environment report. This is inclusive of:</p> <ul style="list-style-type: none"> • 30 metre construction right-of-way; • work spaces; • camp sites; • operational facilities; • dams; and, • access tracks. |
| 2 | <p>To protect the EPBC Act listed Plains Death Adder (<i>Acanthopis hawkei</i>), the approval holder must not:</p> <p>a) disturb more than 791 hectares of suitable Plains Death Adder habitat; and,</p> <p>b) remove more than 36 hectares of suitable Plains Death Adder habitat.</p> | Compliant | <p>Since the commencement of the action, as per Table 3 below, the following occurred concerning the Plains Death Adder (<i>Acanthopis hawkei</i>):</p> <ul style="list-style-type: none"> a) 692 hectares of suitable Plains Death Adder habitat has been disturbed; and, b) 4.8 hectares of suitable Plains Death Adder habitat has been removed to allow for one (1) mainline valve and three (3) cathodic protection stations. <p>All construction work subject to the final public environment report and regulatory approval are complete. No further disturbance or removal of Plains Death Adder habitat is proposed. Vegetation maintenance and erosion repairs have resulted in slashing of vegetation in some areas, however these are likely to grow back throughout the year. It is to be noted that vegetation slashing will be an ongoing annual requirement to maintain the asset integrity.</p> |

| | | | |
|---|---|---------------------|--|
| 3 | For the protection of the EPBC Act listed Plains Death Adder, Carpentarian Antechinus (<i>Pseudantechinus mimulus</i>) and Greater Bilby (<i>Macrotis lagotis</i>), the approval holder must undertake open trench inspection activities in accordance with the Trench Inspection Procedure (Procedure) . | Compliant | <p>All open trench inspections have been in accordance with the Trench Inspection Procedure (version 2) as provided to the Department on 23 February 2017.</p> <p>This version of the Trench Inspection Procedure is available on Jemena's Northern Gas Pipeline Website: https://jemena.com.au/pipelines/northern-gas-pipeline</p> <p>All construction work subject to the final public environment report and regulatory approval are complete. No trenches were excavated during the reporting period.</p> |
| 4 | Within five (5) years of the completion of construction , the approval holder must rehabilitate no less than 791 hectares of suitable Plains Death Adder habitat . | Compliant (ongoing) | <p>Completion of construction occurred during 2018-2019 reporting period. Rehabilitation has commenced as per the approved Rehabilitation Management Plan.</p> <p>The asset is currently in the Transitional Rehabilitation stage. Transitional Rehabilitation Completion criteria is yet to be achieved due to ongoing adverse weather events.</p> <p>A Transitional Rehabilitation Monitoring Report (2025) has been prepared and provided in Appendix A of this report.</p> |
| 5 | <p>The approval holder must submit a Rehabilitation Management Plan for the Minister's approval in writing. The Rehabilitation Management Plan must include:</p> <ul style="list-style-type: none"> a) rehabilitation acceptance criteria; b) procedures, including contingency measures, that will be undertaken to achieve the rehabilitation acceptance criteria; and, c) a monitoring program to determine the success of rehabilitation procedures implemented by the approval holder over the duration of the approval. | Compliant | <p>The Rehabilitation Management Plan was issued to the Minister for approval on 31 March 2017.</p> <p>The Rehabilitation Management Plan is available on Jemena's Northern Gas Pipeline Website: https://jemena.com.au/pipelines/northern-gas-pipeline</p> <p>This document is confirmed to contain:</p> <ul style="list-style-type: none"> a) rehabilitation acceptance criteria; b) procedures, including contingency measures, that will be undertaken to achieve the rehabilitation acceptance criteria; and, c) a monitoring program to determine the success of rehabilitation procedures implemented by the approval holder. |

| | | | |
|---|--|-----------|--|
| | | | A Transitional Rehabilitation Monitoring Report (2025) has been prepared and provided in Appendix A of this report. |
| 6 | The approval holder must not commence the action until the Rehabilitation Management Plan has been approved by the Minister in writing. The approved Rehabilitation Management Plan must be implemented by the approval holder. | Compliant | <p>The Rehabilitation Management Plan was approved on behalf of the Minister on 19 April 2017. No action was commenced until the plan was approved.</p> <p>Transitional Rehabilitation Monitoring Report (2025) has recommended to review and update the Rehabilitation Management Plan as the asset is yet to achieve the transition rehabilitation criteria.</p> |
| 7 | Within 10 days after the commencement of the action, the approval holder must advise the Department in writing of the actual date of commencement . | Compliant | The date of commencement of the Project was 20 May 2017. This was communicated to the Department on 29 May 2017. Refer to Appendix B of this report. |
| 8 | The approval holder must maintain accurate records substantiating all activities associated with or relevant to the conditions of approval, including measures taken to implement the Procedure and management plan required by this approval, and make them available upon request to the Department . Such records may be subject to audit by the Department or an independent auditor in accordance with section 458 of the EPBC Act , or used to verify compliance with the conditions of approval. Summaries of audits will be posted on the Department's website. The results of audits may also be publicised through the general media. | Complaint | <p>All records have been accurately maintained and can be made available to the Department should there be any request to do so.</p> <p>This includes the current 2025 Northern Gas Pipeline Transitional Rehabilitation Monitoring Report which is the basis for this EPBC Annual Report.</p> |
| 9 | <p>Within three (3) months of every 12 month anniversary of the commencement of the action, the approval holder must publish a report (the Annual Compliance Report) on its website describing compliance with each of the conditions of this approval, during the previous 12 months. The approval holder must also provide in this report:</p> <p>a) a reconciliation of actual disturbance and removal of suitable Plains Death Adder habitat (in hectares) on the project area against the</p> | Complaint | <p>a) Reconciliation of actual disturbance and removal of suitable Plains Death Adder habitat (in hectares) on the project area against the disturbance and removal limits specified in condition 2 is provided in Section 1.3 of this report.</p> <p>b) Progress against the Rehabilitation Acceptance Criteria is detailed in Appendix A of this report.</p> |

| | | | |
|----|--|----------------|--|
| | <p>disturbance and removal limits specified in condition 2; and</p> <p>b) progress against the rehabilitation acceptance criteria required at condition 5.</p> <p>Documentary evidence providing proof of the date of the publication must be provided to the Department at the same time as the Annual Compliance Report is published. The approval holder must continue to publish the Annual Compliance Report each year until such time as agreed to in writing by the Minister.</p> | | <p>The Annual Compliance Report is available on Jemena's Northern Gas Pipeline Website:</p> <p>https://jemena.com.au/pipelines/northern-gas-pipeline</p> |
| 10 | <p>The approval holder must report any potential or actual contravention of the conditions of this approval to the Department in writing within two (2) days of the approval holder becoming aware of a contravention.</p> | Not applicable | <p>There has been no contravention to the conditions of this approval to date.</p> |
| 11 | <p>Upon the written direction of the Minister, the approval holder must ensure that an independent audit of compliance with the conditions of approval is conducted and a report submitted to the Minister. The approval holder must not commence the audit until the Minister approves the independent auditor and audit criteria in writing. The audit report must address the criteria to the satisfaction of the Minister.</p> | Not applicable | <p>This did not occur during the reporting period.</p> |
| 12 | <p>The approval holder may choose to revise the Procedure or management plan approved by the Minister under conditions 3 and 5 without submitting it for approval under section 143A of the EPBC Act, if the taking of the action in accordance with the revised Procedure or management plan would not be likely to have a new or increased impact. If the approval holder makes this choice they must:</p> <p>a) notify the Department in writing that the approved Procedure or management plan has been revised and provide the Department, at least four weeks before implementing the revised Procedure or management plan, with:</p> | Not applicable | <p>This did not occur during the reporting period.</p> |

| | | | |
|-----|---|----------------|---|
| | <ul style="list-style-type: none"> i. an electronic copy of the revised Procedure or management plan; ii. an explanation of the differences between the revised Procedure or management plan and the approved Procedure or management plan; and <p>the reasons the approval holder considers that the taking of the action in accordance with the revised Procedure or management plan would not be likely to have a new or increased impact.</p> | | |
| 12A | <p>The approval holder may revoke its choice under condition 12 at any time by notice to the Department. If the approval holder revokes the choice to implement the revised Procedure or management plan, without approval under section 143A of the EPBC Act, the Procedure or management plan approved by the Minister must be implemented.</p> | Not applicable | This did not occur during the reporting period. |
| 12B | <p>If the Minister gives a notice to the approval holder that the Minister is satisfied that the taking of the action in accordance with the revised Procedure or management plan would be likely to have a new or increased impact, then:</p> <ul style="list-style-type: none"> a) condition 12 does not apply, or ceases to apply, in relation to the revised Procedure or management plan; and b) the approval holder must implement the Procedure or management plan approved by the Minister. <p>To avoid any doubt, this condition does not affect any operation of conditions 12 and 12A in the period before the day the notice is given.</p> <p>At the time of giving the notice, the Minister may also notify the approval holder that for a specified period of time that condition 12 does not apply for the Procedure or management plan required under the approval.</p> | Not applicable | This did not occur during the reporting period. |

| | | | |
|----|--|----------------|--|
| 13 | Conditions 12, 12A and 128 are not intended to limit the operation of section 143A of the EPBC Act which allows the approval holder to submit a revised Procedure or management plan to the Minister for approval. | Not applicable | This did not occur during the reporting period. |
| 14 | If, at any time after five (5) years from the date of this approval, the approval holder has not commenced the action, then the approval holder must not commence the action without the written agreement of the Minister . | Not applicable | The date of commencement of the Project was 20 May 2017. This was communicated to the Department on 29 May 2017. Refer to Appendix B of this report. |
| 15 | Unless otherwise agreed to in writing by the Minister , the approval holder must publish the Procedure and Rehabilitation Management Plan on its website. The Procedure and Rehabilitation Management Plan must be published on the website within one (1) month of being approved by the Minister or being submitted under condition 12. The published Procedure and Rehabilitation Management Plan must remain on the website for the lifetime of the approval unless otherwise agreed to in writing by the Minister . | Compliant | The approved rehabilitation management plan has been published on Jemena's Northern Gas Pipeline Website: https://jemena.com.au/pipelines/northern-gas-pipeline |

1.3 PLAINS DEATH ADDER HABITAT DISTURBANCE AND REMOVAL

Table 3 below demonstrates the currently reconciled areas of suitable Plains Death Adder habitat disturbed and removed during the reporting period and since project commencement. To date, these are within the permitted thresholds of this EPBC decision.

Please note that the removal of Plains Death Adder habitat was associated with the construction of the following:

- one mainline valve; and
- three cathodic protection stations.

During this reporting period (20th May 2024 to 19th May 2025), there was no further Plains Death Adder habitat removed. Vegetation maintenance and erosion repairs have resulted in slashing of vegetation in some areas, however these are likely to grow back throughout the year. It is to be noted that vegetation slashing will be an ongoing annual requirement to maintain the asset integrity.

Table 3: Plains Death Adder disturbed and removed habitat

| | Maximum Permitted Quantity ¹ | Previously Reported Reconciled Quantity | Additional Reconciled Quantity for Current Reporting Period | Total Reconciled Quantity Since Project Commencement |
|--|---|---|---|--|
| Plains Death Adder Habitat Area <u>Disturbed</u> | 791 ha | 692 ha | 0 ha | 692 ha |
| Plains Death Adder Habitat Area <u>Removed</u> | 36 ha | 4.8 ha | 0 ha | 4.8 ha |

Note 1: Maximum limit as set out in EPBC Decision 2015/7569

2 APPENDICES

2.1 APPENDIX A – TRANSITIONAL REHABILITATION MONITORING REPORT - 2025


JEMENA NORTHERN GAS PIPELINE TRANSITIONAL REHABILITATION ASSESSMENT REPORT 2025



Report prepared for Jemena Ltd.
August 2025

Prepared by:

Low Ecological Services P/L
PO Box 3130, Alice Springs, NT 0871
Ph: (08) 89 555 222
Email: lowecol@lowecol.com.au
Web: www.lowecol.com.au





Frontispiece: Top - cattle using pipeline signage as a scratching post. Bottom - revegetation on the ROW at KP 350.

DISCLAIMER

This document has been prepared by Low Ecological Services (LES) for Jemena Ltd. LES has prepared this document using the skill and care expected from professional scientists to provide factual and technical information and reasonable solutions to identified risks. It does not constitute legal advice.

DOCUMENT CONTROL

| Approvals | Name | Signature | Date |
|--------------|----------------|--|------------|
| Prepared by: | K. Ward |  | 01/08/2025 |
| Approved by: | Bill Low |  | 06/08/2025 |
| Jemena: | Rahul Dorairaj | | 11/08/2025 |

REVISION DETAILS

| Date | Revision | Author/Reviewer | Company | Comments |
|------------|----------|-----------------|-------------------------|-----------------------------|
| 01/08/2025 | V1 | K. Ward | Low Ecological Services | Draft V1 |
| 16/08/2025 | V2 | K. Ward | Low Ecological Services | Updated after Jemena review |

EXECUTIVE SUMMARY

The Northern Gas Pipeline (NGP) is a 622 km buried gas pipeline linking existing gas pipelines in the Northern Territory (NT) and Queensland (Qld). The NGP is currently in the transitional rehabilitation phase which involves returning disturbed areas to a stable, non-polluting landform, the return of native species, and the control of weed species. The transitional rehabilitation phase monitors the progress of rehabilitation ensuring that it is transitioning towards final rehabilitation. Meeting the transitional rehabilitation criteria is the responsibility of Jemena Ltd. Monitoring will be conducted annually for the first five years following completion of construction (or until the transitional rehabilitation criteria are met). The 2024 survey, the fifth transitional rehabilitation assessment of the NGP project area found that the project had not met the transitional rehabilitation criteria and further remediation activities and surveys were required. This report documents the sixth transitional rehabilitation assessment of the NGP project area.

The survey was conducted over 7 days from the 23rd - 29th June 2025. The NGP ROW was traversed from west to east in 4WD vehicles. Locations inspected during the survey included the ROW, construction areas, waterway crossings, and areas of works conducted since the completion of the pipeline. Sites identified in previous transitional rehabilitation assessments as not meeting the criteria were also reassessed. Similar to previous years, assessment focused on three key rehabilitation factors; weed infestation, land stability, and revegetation. Additionally, targeted plains death adder (*Acanthophsis hawkei*) habitat surveys were conducted in the Mitchell Grass Downs bioregion to assess compliance with EPBC 2015/7569 Condition 4.

WEEDS (Section 4.1)

Transitional rehabilitation criteria in relation to weeds was not met: “*No weed incursion or spread within the NGP footprint.*”

The presence of weeds along the pipeline easement was similar to previous years (LES 2023, LES 2024). Some species have increased, especially kapok at the eastern end of the easement. There were very few instances of weeds previously recorded that could not be found on this survey. Several new areas of weed infestation were identified that were not recorded in 2024.

Weed occurrences were typically in low density within the ROW and mostly the result of encroachment from adjacent pastoral land. Declared weed species recorded during the survey included Noogoora burr and mesquite, both of which should be prioritised for management.

Recommendations regarding management of non-declared weed species remain the same as advice provided in 2024 (LES). High density populations should be targeted to prevent further spread along the easement and into adjacent land. In particular, the populations of kapok bush near KP 566, and the eastern most 40 km stretch of the ROW, have increased in size and continue to spread into the surrounding landscape and westerly along the ROW.

Ongoing management and working in conjunction with local landholders is required to reduce the spread of weed species along the easement and into surrounding lands.

LAND STABILITY

Transitional rehabilitation criteria in relation to land stability was not met: *“Disturbed areas are a stable landform within 12 months.”*

A significant portion of the ROW meet this criterion. However, there remain areas of erosion, subsidence, and ineffective and deteriorating berms at multiple locations along the ROW. While the majority of these issues are minor, management action is required to achieve a stable landform along the pipeline in areas identified as having moderate to significant land stability issues.

The transitional rehabilitation criteria also requires disturbed areas to be re-profiled to contours consistent with the surrounding landform. This criterion was met in 2023, however it was noted in the 2024 and 2025 assessments that areas of the ROW had become lower than the surrounding landscape. This lowering was likely a result of removal of material through sheet flow erosion, grading over the ROW and/or repeated vehicle access on the ROW.

Grading activities are likely to increase susceptibility to erosion both in areas where berms had been removed, and in areas where grading has formed windrows. Windrows have the potential to redirect water flow along the ROW and encourage erosion by preventing water from leaving the easement.

Personnel carrying out pipeline maintenance activities including grading and vegetation clearing should be informed regarding transitional rehabilitation criteria goals and the most appropriate methods of remediation to prevent further issues.

Erosion (Section 4.2.1)

The overall level of erosion over the extent of the ROW observed in the 2025 survey was low. Erosion was recorded at numerous locations along the easement; however, approximately 60% of these instances were classified as minor, and only 5% were considered moderate to severe. In areas of berm removal, sheet erosion had increased. Remediation work has decreased erosion along the length of the pipeline easement since it was last surveyed in 2024.

As noted in previous surveys (LES 2023, LES 2024), the majority of erosion was confined to the access track within the ROW, where limited vegetation cover increased susceptibility to erosion. The most common form of erosion was sheet erosion. Significant portions of the ROW had high coverage of vegetation making it difficult to accurately assess those areas for erosion, this may have led to underreporting.

As a priority, it is recommended that all severe to moderate erosion should be remediated by constructing multiple series of shallow berms and back-filling and leveling where appropriate.

Minor erosion should continue to be monitored and if earthworks equipment is in the area, shallow berms should also be constructed to prevent these from worsening over time.

Compromised berms (Section 4.2.2)

It is difficult to compare the number of compromised berms in 2025 compared to previous years as grading activities on the western end of the pipeline has resulted in the complete removal of multiple berms. In these areas, multiple series of shallow trafficable berms must be re-constructed to prevent erosion on the ROW.

Of the berms that remain, 42 berms are compromised. Damage was most often due to water erosion resulting in erosion channels through the berms or the berms being washed out. There were several occurrences of water flowing around the ends of berms and back onto the ROW rather than diverting outwards into adjacent land. This was often due to berms not extending far enough at the edges of the ROW. Cattle tracking has also caused erosion of berms in some instances, as well as vehicle activity along the access track of the ROW.

All compromised berms should be repaired or reinstated promptly. Additional berms are also required in several locations along the ROW as indicated in Appendix A, Table 9-9-2.

Subsidence (Section 4.2.3)

Subsidence issues were recorded at several locations on the ROW. The majority of subsidence issues observed were associated with water channelling and erosion across the pipeline or along the pipeline trench, with several locations attributed to cattle and vehicle tracks. Filling in of subsidence is recommended in all instances of significant, significant/moderate and moderate subsidence issues, some of those will require erosion control berms with monitoring recommended for minor subsidence issues.

REVEGETATION (Section 4.4)

Transitional rehabilitation criteria in relation to revegetation has not been wholly met: *“Ground cover which is not a declared species is growing in disturbed areas within 12 months of the completion of construction activities and maintained.”* The transitional rehabilitation of the NGP ROW continues to progress and is estimated to be approximately 85% complete. Transitional rehabilitation was assessed as 95% and 90% complete in the 2023 and 2024 reports respectively, the reduction in percent complete is due to vegetation clearing to meet pipeline Australian Standards AS 2885. This has removed ground cover from highly rehabilitated areas, leading to an interim reduction in rehabilitation. Ensuring topsoil remains after grading works is essential for regrowth of grasses and low shrubs in these areas.

Overgrowth

On several sections of the ROW, dense overstorey vegetation was recorded which require clearing to meet AS 2885 minimum management requirements of vegetation within the pipeline corridor to provide access and ensure visibility of pipeline warning signs and the pipeline trench.

There was less overgrowth observed in 2025 compared to 2024 as additional sections of the pipeline clearing had been undertaken. Vegetation and topsoil cleared off the ROW has been pushed off to the side in piles. The piles contain high nutrient soil as well as seed bank for grasses, both of which will encourage rapid rehabilitation. It is recommended that these piles be redistributed along areas of the pipeline which require fill material or used to construct shallow bunds, with precautions for fauna safety that may have taken up residence in these piles. Regular ongoing maintenance to prevent an overstorey re-establishing along the ROW in the future will be required.

The continued removal of the overstorey vegetation overgrowth on the pipeline easement remains a priority. During the clearing process, land stability issues can be rectified, and soil stabilisation and berms can be repaired and added where appropriate.

PLAINS DEATH ADDER HABITAT

Transitional rehabilitation criteria in relation to suitable Plains Death Adder habitat was incomplete: *“No less than 791 ha of suitable Plains Death Adder habitat is rehabilitated within 5 years of completion of construction.”*

Habitat for the threatened Plains Death Adder extending from KP 355 to KP 561 continues to show increased rehabilitation with each survey. Cracks and holes along the appropriate habitat are forming and vegetation cover is high creating habitat appropriate for hunting and temporary shelter for Death Adders. Detailed vegetation surveys comparing plant species adjacent to and on the ROW indicate species composition on the ROW is not yet 70% equivalent of vegetation off the ROW; more time is required for a range of species to reestablish although the major Mitchell and other mid-grasses is similar both on and off the ROW. It is important to protect this section from clearing or other major works with heavy machinery.

REHABILITATION MANAGEMENT PLAN

The original RMP states that if there is a delay in progress towards meeting the rehabilitation completion criteria over two consecutive years, then a review of the RMP should be undertaken. A number of events and circumstances over the last two years, such as uncontrollable natural events, and proximity to culturally sensitive land has delayed Jemena meeting the transitional rehabilitation criteria.

Table of Contents

| | |
|--|----|
| EXECUTIVE SUMMARY | ii |
| Glossary..... | 1 |
| Abbreviations | 1 |
| 1. INTRODUCTION | 2 |
| 1.1. Background..... | 2 |
| 1.2. Scope | 4 |
| 1.3. Regulatory framework..... | 4 |
| 1.3.1. AS 2885: Australian Standard for High Pressure Pipeline Systems (2022) | 4 |
| 1.3.2. Pipeline Integrity Management Plan (GAS-300-PA-IN-002) (2022) | 4 |
| 1.3.3. Northern Territory Environment Protection Authority Assessment Report 79 (2017) 4 | |
| 1.3.4. Rehabilitation Management Plan (GAS-399-PA-EV-002) (2017)..... | 5 |
| 1.3.5. APGA Code of Environmental Practice 2013 | 6 |
| 2. EXISTING ENVIRONMENT | 7 |
| 2.1. Rainfall..... | 7 |
| 2.2. Fire History | 8 |
| 2.3. Biogeographic regions | 1 |
| 2.4. Land Systems | 2 |
| 3. METHODOLOGY..... | 4 |
| 3.1. Weeds | 4 |
| 3.2. Land Stability | 4 |
| 3.3. Revegetation..... | 5 |
| 3.4. Plains Death Adder Habitat..... | 5 |
| 4. FIELD SURVEY RESULTS..... | 7 |
| 4.1. Weeds | 7 |
| 4.2. Land Stability | 14 |
| 4.2.1. Erosion | 14 |

| | | |
|--------|--|----|
| 4.2.2. | Compromised Berms | 19 |
| 4.2.3. | Subsidence | 22 |
| 4.3. | Land Stability Remediation | 25 |
| 4.4. | Revegetation/Overgrowth | 27 |
| 4.5. | Infrastructure..... | 32 |
| 4.6. | Plains Death Adder Habitat Survey..... | 36 |
| 5. | ASSESSMENT OF TRANSITIONAL COMPLETION CRITERIA | 43 |
| 6. | RISKS TO REHABILITATION OBJECTIVES | 46 |
| 7. | CONCLUSION AND RECOMMENDATIONS | 48 |
| 7.1. | Weeds | 48 |
| 7.2. | Land Stability | 49 |
| 7.3. | Revegetation and Overgrowth | 50 |
| 7.4. | Plains Death Adder Habitat..... | 51 |
| 7.5. | Review of the Rehabilitation Management Plan Error! Bookmark not defined. | |
| 8. | REFERENCES | 52 |
| 9. | APPENDICES..... | 53 |

List of Tables

| | | |
|----------|--|----|
| Table 1. | Surveys conducted to date in the NGP footprint..... | 3 |
| Table 2. | Biogeographic regions intersecting the NGP ROW..... | 1 |
| Table 3. | Land systems intersecting the NGP ROW..... | 2 |
| Table 4. | Introduced flora species observed during the survey..... | 8 |
| Table 5. | Number of erosion instances in 2024 vs 2025..... | 14 |
| Table 6. | Summary of plains death adder habitat survey data..... | 36 |
| Table 7. | List of all flora species recorded in quadrats..... | 37 |
| Table 8. | Percentage of vegetation cover..... | 38 |
| Table 9. | Cracks and holes recorded on and off the ROW. | 38 |

| | |
|--|----|
| Table 10. Assessment of transitional rehabilitation criteria. | 43 |
| Table 11. Risks to transitional rehabilitation completion. | 47 |

List of Figures

| | |
|---|----|
| Figure 2-1. Total rainfall in Tennant Creek (NT), Camooweal (Qld) and Mount Isa (Qld) from January 2020 to June 2025 (inclusive). | 7 |
| Figure 2-2. Fire activity along NGP ROW between January 2023 and June 2025. | 1 |
| Figure 2-3. Land systems intersecting the NGP ROW. | 3 |
| Figure 3-1. Plains death adder habitat survey sites MG01-MG14 on the NGP. Note MG06 is approximate only. | 6 |
| Figure 4-1. Introduced flora species observed during the survey displayed by weed classification. Refer to Table 4 for state and territory categories. | 12 |
| Figure 4-2. Images from the transitional rehabilitation assessment survey: a) Kapok bush along vehicle road on ROW, b) Spiky acacia, c) Kapok bush and erosion d) Mesquite e) Noogoora burr at base of infrastructure, likely from cattle scratching, f) multiple weed species including malvastrum, Noogoora burr and spiky acacia. | 13 |
| Figure 4-3. Locations of erosion observed on the NGP ROW in 2025. | 16 |
| Figure 4-4. Images from the transitional rehabilitation assessment survey: a) Windrow that needs to be brought in, b) grading creating height difference c) overgraded section with berms removed, windrows built up and sheet erosion (level 5). | 17 |
| Figure 4-5. Images from the transitional rehabilitation assessment survey: a) erosion at a creek crossing, b) level 4 erosion, c) level 3 erosion, d) level 1 erosion, e) level 2 erosion. | 18 |
| Figure 4-6. Locations of compromised berms observed on the NGP ROW in 2025. | 20 |
| Figure 4-7. Images from the transitional rehabilitation assessment survey: a) berm has been removed in recent grading works b) compromised berm. | 21 |
| Figure 4-8. Locations of observed subsidence along the NGP ROW in 2025. | 23 |
| Figure 4-9. Images from the transitional rehabilitation assessment survey: a) level 2 subsidence, b) level 4 subsidence. | 24 |
| Figure 4-10. Image from the transitional rehabilitation assessment survey: remediated erosion. | 25 |

| | |
|--|----|
| Figure 4-11. Location of additional remediation works required on the ROW. | 26 |
| Figure 4-12. Overgrowth along the NGP ROW observed in 2025..... | 29 |
| Figure 4-13. Images from the transitional rehabilitation assessment survey: a) level 5 vegetation, shrubs require clearing, landholder maintains road clear as effective fire break, b) level 2 vegetation, lack of topsoil impeding revegetation, c) and d) level 5 vegetation, shrubs require removal. | 30 |
| Figure 4-14. Images from the transitional rehabilitation assessment survey: a) level 5 vegetation with no shrubs, b) level 1 vegetation caused by grading, c) cattle tracks through vegetation, d) level 5 vegetation in comparison to surrounds, e) level 5 vegetation with some shrubs that will require clearing, f) level 5 vegetation with whitewood in easement, high priority to clear as growing over pipeline. | 31 |
| Figure 4-15. Locations of damaged infrastructure observed on the ROW in 2025..... | 33 |
| Figure 4-16. Images from the transitional rehabilitation assessment survey: a) fallen sign, b) damaged pole with exposed wires, c) burned sign, d) cattle using sign as scratching post. | 34 |
| Figure 4-17. Vegetation posing a potential fire risk inside the fencing at Main Line Valve 3. | 35 |
| Figure 4-18. Vegetation on the ROW similar to vegetation off the ROW but not yet meeting transition criteria..... | 39 |
| Figure 4-19. Images from assessment survey. Mitchell grasses recovering well in general. (a) KP 400 vegetation cover on the ROW representative of vegetation off the ROW, (b) cattle tracks following the ROW, impacting vegetation cover and (c) less vegetation cover on the ROW compared to off the ROW. | 40 |
| Figure 4-20. Blue tongue lizard using crack formed on the ROW. | 41 |
| Figure 4-21. Examples of cracks and holes on the ROW. | 42 |

GLOSSARY

Ground cover: Low-growing native herbaceous flora, such as grasses, forbs and ferns.

Laydown area: Sites which were cleared during the construction of the pipeline to store materials for the pipeline.

Overstorey: The woody mid and upper story vegetation which obstructs view of the soil surface and can send roots to the depth of the gas pipe, impacting the integrity of the pipe.

Topsoil: The uppermost layer of soil, rich in organic matter, microorganisms, and seeds, which are essential for natural revegetation processes.

ABBREVIATIONS

| | |
|------|---|
| APGA | Australian Pipelines and Gas Association |
| CoEP | APGA Code of Environmental Practice |
| CP | Cathodic protection |
| EPBC | Environment Protection and Biodiversity Conservation Act 1999 |
| EPA | Northern Territory Environment Protection Authority |
| KP | Key points – every kilometre along the length of the pipeline from KP 0 at the Phillip Creek Compressor Station to KP 622 at the Mount Isa Compression Station. |
| MLV | Main line valve |
| NGP | Northern Gas Pipeline |
| PIMP | Pipeline Integrity Management Plan |
| RMP | Rehabilitation Management Plan |
| ROW | Right of way - The 30 metre wide corridor in which the pipeline is laid and where pipeline maintenance activities occur. |
| WONS | Weed of national significance |

1. INTRODUCTION

1.1. Background

The Northern Gas Pipeline (NGP) is a 622 km buried gas pipeline linking existing gas pipelines in the Northern Territory (NT) and Queensland (Qld). Construction of the pipeline commenced on 20th May 2017, with Jemena Ltd. taking control of the site from the construction contractors in June 2018, and the pipeline becoming operational on 3rd January 2019.

The NGP commences at the Phillip Creek Compressor Station, approximately 45 km north-west of Tennant Creek, and terminates 7 km south-west of Mount Isa at the Mount Isa Compression Station. The NGP project area comprises of a 30 m wide Right of Way (ROW), temporary workspaces and camp sites, operational facilities, dams, and access tracks.

Approval for the NGP was dependent on the development and implementation of a Rehabilitation Management Plan (RMP) that incorporated the requirements of the three interested jurisdictions – NT, Qld, and the Commonwealth. Of particular interest to the Commonwealth was the restoration of habitat for the threatened plains death adder (*Acanthophis hawkei*) found in the Barkly Tablelands between key points (KP) KP 355 - KP 561 of the NGP ROW.

The RMP states that the ROW and all temporary facilities will be progressively rehabilitated on completion of the construction phase. The only components to be retained long term are permanent facilities (compressor stations, main line valve (MLV) and cathodic protection (CP) stations) and their associated access tracks and any access tracks or dams requested by the landholder.

The RMP defined three phases to rehabilitation:

- **Reinstatement:** *The process of bulk earthworks and structural replacement of pre-existing conditions of a site (i.e. backfilling of trench, reinstating soil surface topography including scouring or ripping, watercourse lines, culverts, fences and gates and other landscape features). It also includes placing cleared vegetation across disturbed areas. Reinstatement occurs during the construction phase and is the responsibility of the Construction Contractor.*
- **Transitional rehabilitation:** *The process of returning disturbed areas to a stable, non-polluting landform, the return of native species and the control of weed species. It differs from the reinstatement phase in that it generally does not involve bulk earthworks, but instead monitors the progress of rehabilitation ensuring that it is transitioning towards final rehabilitation, where an issue is found it is to be rectified. Transitional rehabilitation monitoring will focus on areas where failure risk is high. These include erosion at watercourse crossings; weeds at construction weed hygiene locations and preventing any weed incursion.*

- **Rehabilitation:** *The process of returning a site's structural habitat complexity, and ecosystem processes and services to that of the pre-existing conditions at the site or an analogue site.*

Meeting the transitional rehabilitation criteria is the responsibility of Jemena. The RMP states that monitoring of the transitional rehabilitation phase is to be conducted annually for the first five years and then every five years following the transitional rehabilitation criteria being met for three consecutive years. If the rehabilitation criteria are not met within five years of the transitional rehabilitation period finishing, the RMP is to be reviewed taking into consideration the monitoring results to ensure rehabilitation criteria are eventually met. Once the rehabilitation criteria are met, two additional rehabilitation monitoring events will be undertaken to ensure that the rehabilitation is stable. That is, three consecutive annual surveys must demonstrate that the rehabilitation criteria have been attained/maintained before cessation of rehabilitation condition monitoring may be considered. Following the rehabilitation criteria being met over a three-year period, a final rehabilitation report will be prepared, published and submitted to regulators.

The NGP is currently in the sixth year of the transitional rehabilitation phase. In addition to weeds, land stability and revegetation, this survey included targeted vegetation and habitat surveys in plains death adder habitat to determine if plant species composition on the ROW contains 70% of the species found in adjacent comparable habitat (ie similar soils, topography and drainage criteria).

There is quality habitat for the threatened plains death adder on the ROW in the Barkley, Georgina, Wonardo, Austral, Wonorah-Barkley and Kalalla land systems (KP 355 to KP 561). The EPBC License which extends to 2027 also states the requirements for return of the total length of Death Adder habitat, 791 ha, less xx ha of land for infrastructure construction, and habitat monitoring frequency.

Table 1. Surveys conducted to date in the NGP footprint.

| Year | Survey Details |
|------|--|
| 2020 | Land stability and revegetation (EcOz, 2020). |
| 2021 | Weeds, land stability, and revegetation (LES 2021). |
| 2022 | Weeds and land stability (Jemena 2022). |
| 2023 | Weeds, land stability, and revegetation (LES 2023). NT Government Transitional Rehabilitation Assessment (NT Government 2023) |
| 2024 | Weeds, land stability, and revegetation (LES 2024). |
| 2025 | Weeds, land stability, revegetation, and plains death adder assessment. |

1.2. Scope

The scope of this report is to assess the current status of transitional rehabilitation across the NGP project area. In this assessment, the focus is on weeds, land stability, and revegetation with reference to the RMP transitional rehabilitation criteria, as discussed in Section 0 of this report. In areas where the criteria are not met, remediation recommendations are provided in Section 7. Jemena agreed to a proposal to begin monitoring of habitat quality for Death Adders in the Barkly Tableland clay soils to allow assessment of meeting rehabilitation requirements for Death Adder habitat.

1.3. Regulatory framework

1.3.1. AS 2885: Australian Standard for High Pressure Pipeline Systems (2022)

AS 2885 was adopted by the Council of Australian Governments in its communiqué of 25th February 1994 in which it agreed to adopt AS 2885 to achieve uniform national pipeline construction standards by the end of 1994. AS 2885 provides an authoritative source of fundamental principles and practical guidelines for use by responsible and competent persons or organisations. It is the foundation on which the high-pressure pipelines sector provides assurance to itself, policy makers, regulators and the wider community that the pipelines that carry very hazardous materials at high pressure (i.e. hydrocarbons, hydrogen, CO₂ and other fluids) are safe, environmentally benign and reliable. AS 2885 is considered to be 'single and sufficient' for design, construction, maintenance and operations of pipeline systems carrying fluid at high pressures, because it is comprehensive in the matters that need to be covered by pipeline technical regulation and there is no need for the State technical regulators to make further or additional technical regulations.

1.3.2. Pipeline Integrity Management Plan (GAS-300-PA-IN-002) (2022)

The Pipeline Integrity Management Plan (PIMP) outlines the integrity requirements and controls as determined by the NGP design and Jemena's integrity management process and includes references to procedures, plans and other documentation. Jemena manages the integrity of the NGP in compliance with AS 2885.

1.3.3. Northern Territory Environment Protection Authority Assessment Report 79 (2017)

The Northern Territory Environment Protection Authority (NT EPA) prepared Assessment Report 79 in accordance with section 7(2)(g) of the Environmental Assessment Act 1982 and clause 14(3) of the Environmental Assessment Administrative Procedures. The purpose of this report is to ensure that matters affecting the environment to a significant extent are fully examined and reported. The report was provided to the Northern Territory Ministers for Environment and Natural Resources (the Minister) and Primary Industry and Resources (the

responsible Minister) to be considered in decisions made by the Northern Territory Government; it does not provide an environmental approval.

1.3.4. Rehabilitation Management Plan (GAS-399-PA-EV-002) (2017)

The RMP was developed to fulfil the requirements of the environmental approvals processes for the NGP project, in particular Condition 5 of the EPBC approval dated 9th March 2017. The RMP covers the entire length of the pipeline including all areas within the project area in both the NT and Qld.

The primary objective of the RMP is to return the land to comparable state to the pre-construction condition such that it can support a suitable land use and function as plains death adder habitat. The RMP describes the rehabilitation management measures that will be implemented to mitigate identified environmental impacts and meet the relevant rehabilitation criteria. There are three phases to the RMP: reinstatement, transitional rehabilitation, and rehabilitation.

Plains Death Adder Habitat

Condition 4 of the EPBC approval pertains to plains death adder habitat rehabilitation and states

Within five (5) years of the completion of construction, the approval holder must rehabilitate no less than 791 hectares of suitable Plains Death Adder habitat.

The RMP outlines rehabilitation completion criteria in section 4.3.1:

The following criteria has been specified to achieve successful rehabilitation of disturbed areas.

All significantly disturbed areas caused during construction of the NGP which are not being or intended to be utilised by the landholder or overlapping tenure holder, must be rehabilitated to meet the following final acceptance criteria measured either against the highest ecological value adjacent land use or the pre-disturbed land use:

- (a) greater than or equal to 70 % of native ground cover species richness*
- (b) greater than or equal to the total per cent of ground cover*
- (c) less than or equal to the per cent species richness of declared plant pest species; and*
- (d) where the adjacent land use contains, or the pre-clearing land use contained, one or more regional ecosystem(s), then at least one regional ecosystem(s) from the same broad vegetation group, and with the equivalent biodiversity status or a biodiversity status with a high conservation value as any of the regional ecosystem(s) in either the adjacent land or pre-disturbed land, must be present.*

No less than 791 ha of suitable Plains Death Adder habitat is rehabilitated within 5 years of completion of construction.

Rehabilitation of suitable Plains Death Adder habitat will be complete when the above completion criteria are met.

This report addresses the condition of the plains death adder habitat six years after the completion of construction.

1.3.5. APGA Code of Environmental Practice 2013

The Australian Pipelines and Gas Association (APGA) Code of Environmental Practice (CoEP) provides industry accepted guidance on environmental management through the planning and asset acquisition, construction, operational and decommissioning phases of a pipelines' lifecycle. The CoEP focuses on the key activities conducted during different pipeline lifecycle phases, and the potential environmental risks that arise from these activities. The CoEP has been developed by APGA in consultation with its membership, the former Australian Gas Association, the Australian Petroleum Production and Exploration Association and pipeline regulating authorities in each Australian State and Territory.

2. EXISTING ENVIRONMENT

2.1. Rainfall

The NGP project area is in an arid climate characterised by low (<380 mm/year on average) and highly variable rainfall. Rainfall affects rehabilitation through plant recruitment and erosional processes. The rainfall pattern across the project area is driven by monsoonal or cyclonic events to the north resulting in higher rainfalls in summer. La Niña has also affected rainfall in the NGP project area with a significant increase during the 2022/2023 and 2023/2024 summer periods in comparison to other years. Rains in 24/25 were patchy with some extended dry periods but with periodic large falls of rain, particularly January, March and June, 2025. The large amount of rain resulted in extensive vegetation growth along the pipeline, particularly shrubs in the desert and mountain country, and perennial and annual grasses in the black soil country. Rainfall also exacerbated erosion issues and assisted in the spread and proliferation of weed species.




Figure 2-1. Total rainfall in Tennant Creek (NT), Camooweal (Qld) and Mount Isa (Qld) from January 2020 to June 2025 (inclusive).

2.2. Fire History

Australia's biggest bushfire season in more than a decade occurred in 2023. Between September and October 2023 more than 18 million hectares burnt in the Barkly, Tanami and Great Sandy Deserts of the Northern Territory and Western Australia. La Niña was the major driver of these fires. The high rainfall increased vegetation growth, resulting in a greater fuel load. Fires caused by lightning strikes increase when weather conditions are extreme, and fuel is dry. Fire removes the plants and organic material that naturally stabilises soil, therefore making it more prone to erosion (Natural Resources SA, 2015). Large areas of the NGP were affected by the 2023 fires (Figure).

A very small portion of the pipeline easement was burned in 2025 at the western end. In the 2025 field survey, there was evidence of a recent burn on the eastern end of the pipeline close to Mount Isa which is not captured in the map below.




Figure 2-2. Fire activity along NGP ROW between January 2023 and June 2025.

2.3. Biogeographic regions

The Interim Biogeographic Regionalisation of Australia (IBRA) provides a division of Australia in geographically distinct bioregions based on common climate, geology, landform, native vegetation, and species information (Thackway & Cresswell, 1995). The NGP ROW falls within four biogeographic regions described in Table 2.

Table 2. Biogeographic regions intersecting the NGP ROW.

| Region | Description |
|---------------------------------|---|
| Davenport Murchison Ranges (NT) | Area: 58,050 km ² , characterised by a chain of rocky ranges surrounded by lowland plains. Vegetation is predominantly eucalypt low, open woodland and acacia-sparse shrubland over hummock grassland. Semiarid to subtropical climate, most rainfall occurs in summer and is higher in the north of the bioregion. Spatially averaged median (1890–2005) rainfall is 289 mm. |
| Tanami (NT) | Area: 259,970 km ² , characterised by featureless sand plains with small areas of alluvial plains, low ridges and stony rises. Vegetation is predominantly spinifex hummock grassland with a tall-sparse shrub overstorey. Climate is semiarid with a monsoonal influence. Rainfall is summer dominant and the spatially averaged median (1890–2005) rainfall is 298 mm. |
| Mitchell Grass Downs (Qld) | Area: 335,320 km ² , characterised by largely treeless plains with some occasional ridges, rivers and gorges. The dominant vegetation type is Mitchell tussock grasslands. Dry monsoonal to semiarid climate in the south and subhumid tropical climate in the north. Spatially averaged median (1890–2005) rainfall is 332 mm, but some parts receive more than 500 mm each year. |
| Mount Isa Inlier (Qld) | Area: 66,640 km ² , characterised by rugged hills and mountain ranges separated by undulating valleys. The predominant vegetation is low open woodland over spinifex hummock grassland. Hot and semiarid climate with summer-dominant rainfall. Spatially averaged median (1890–2005) rainfall is 388 mm. |

2.4. Land Systems

Land systems have long been used as classification units and are suggested as effectively representing broad patterns of different biological assemblages across the landscape (Oliver, 2004). The NGP ROW intersects several land systems which are described in Table 3 and mapped in Figure .

Table 3. Land systems intersecting the NGP ROW.

| Land System | Description |
|----------------|--|
| Austral | Several small areas of gently undulating Mitchell grass plains near Brunette Downs homestead in the Barkley Basin and between Austral Downs and Carandotta Homesteads in the Georgina Basin. |
| Barkly | Very gently undulating to nearly flat Mitchell grass plains covering much of the area commonly referred to as the Barkly Tableland. |
| Bundella | Undulating, sandy, low-scrub country extending from Barkly Downs Homestead and south towards Admore Homestead. |
| Camil | This gently undulating country with spinifex and low shrubs has leached limestone soils; it occurs as one large and several small areas west of Lake Nash Homestead. |
| Camilrock | Several small areas of gently undulating country with numerous limestone outcrops and carrying spinifex and low shrubs to the west and north-west of Lake Nash Homestead. |
| Georgina | Flat to gently undulating plains and alluvial plains. Slopes 0-4% and mainly <2%. |
| Gosse | Several small, scattered areas of sandy, seasonally flooded flats in the south-west "desert" portion of the region. |
| Kalalla | Flat to very gently undulating plains with occasional internal drainage depression. Slopes <2%. |
| Mt Isa | This lightly timbered, rugged, hilly country with north-south ridges extend from the south-east corner of the area to about 193 km north and west of Lawn Hill Homestead. |
| Prentice | Gently undulating country carrying scrubby vegetation and occurring between Wonorah and Frewina on the Barkly Highway. |
| Tennant Creek | An area of lightly timbered flat-topped hills and broad valleys in the south-west corner of the region. |
| Waverly | A broken strip of hilly lightly timbered granite country with mostly steep to moderate slopes which extends from the south-east corner of the region to the north of Mt. Isa. |
| Wonardo | Irregular areas of gently undulating to nearly flat Mitchell grass plains confined to the Georgina valley in the south-east portion of the region. |
| Wonorah | Gently undulating country with deep lateritic soil and low scrubby vegetation. There is one large area in the south-west and numerous scattered areas in the central and eastern portions. |
| Wonorah-Barkly | Gently undulating country with deep lateritic soil and low scrubby vegetation. There is one large area in the south-west and numerous scattered areas in the central and eastern portions. |
| Yelvertoft | Numerous widely separated areas of undulating timbered country in the south half of the region with gravelly and stony lateritic soils. |




Figure 2-3. Land systems intersecting the NGP ROW.

3. METHODOLOGY

The NGP ROW was traversed from west to east in two 4WD vehicles. The survey was conducted over 7 days from the 23rd - 29th June 2025, with the two vehicles leapfrogging each other to survey approximately 25 km at a stretch.

Key point (KP) locations marked along the pipeline denote distance (kilometres) from the western end of the NGP, starting at the gate to the Phillip Creek Compressor Station (KP0). The survey was broken down into 25 sections, with 25 kilometres in each section e.g. KP0 - KP25, with the exception of the final section which was 22 kilometres (KP600 - KP622). Data collected for Map 18 (KP 425 to KP 450) was lost due to a technological issue.

Locations inspected during the survey included the ROW, laydown areas, waterway crossings, and areas of works conducted since the completion of the pipeline. Locations identified in previous transitional rehabilitation assessments as not meeting the criteria were also assessed.

Observations, photos and notes were recorded on tablets using the Avenza Maps application and GPS devices and were subsequently analysed using QGIS mapping tools.

Four key rehabilitation indicators were assessed; weed infestation, land stability, revegetation, and plains death adder habitat rehabilitation. Assessment methodologies for each rehabilitation factor are outlined below.

3.1. Weeds

Identified weed species and locations were recorded with a description and classification of density within the NGP ROW and the adjacent land. Weeds recorded were both declared species and non-declared species. Photos were taken to demonstrate density for declared species. All previously recorded weed locations were assessed and compared where relevant.

3.2. Land Stability

Land stability issues, such as erosion, subsidence, and compromised berms were recorded with a description of the instability that had occurred as well as remediation recommendations.

All issues were given a score between 1-5 reflecting the severity of the issue:

1. Significant issues that require remediation.
2. Moderate issues that could become significant and require remediation.
3. Moderate issues that require remediation.
4. Minor issues that require monitoring.
5. Very minor issues that require monitoring.

Previously recorded land stability issues were assessed and compared where relevant.

3.3. Revegetation

Revegetation condition was recorded along the entirety of the pipeline easement. The assessment focused on the level of vegetation cover to identify the efficacy of revegetation methods, particularly in assisting land stability and ensuring suitable native species were regenerating. The similarity of revegetation species composition to surrounding remnant vegetation and the relevant land systems was broadly considered however species compositions were not assessed in detail.

All areas were given a score between 1-5 reflecting the state of revegetation:

1. No revegetation evident in any stratum.
2. Vegetation cover is sparse and limited to one or two strata, is in poor condition and/or has weed infestations.
3. Moderate vegetation cover and condition in either ground or shrub stratum, may include sparse vegetation in other relevant stratum, species composition broadly suitable to relevant land system.
4. Moderate to dense vegetation cover in two or more stratum, species composition suitable to relevant land system.
5. Excellent vegetation cover in all relevant strata, condition, and species composition comparable to adjacent vegetation and relevant land system.

All previously recorded revegetation classifications and comments were assessed and compared where relevant.

3.4. Plains Death Adder Habitat

Targeted habitat surveys were conducted at 14 locations (MG01-MG14) along the ROW in the Mitchell Grasslands, six in the NT and eight in Qld.

At each site, all flora species were documented within two 100 m² quadrats: one located on the ROW and the other in adjacent, equivalent habitat off the ROW. Ground cover characteristics (including plant species, non-vegetative cover such as rock or bare ground) were recorded at 1-metre intervals along two 100-metre transects, both on and off the ROW. The number of soil cracks holes observed along each transect was also recorded.

For each site, the composition of vegetation species was compared in the transect on the pipeline with the quadrat off the pipeline. The target for rehabilitation was 70% of species that occurred off the ROW should also occur on the ROW.




Figure 3-1. Plains death adder habitat survey sites MG01-MG14 on the NGP. Note MG06 is approximate only.

4. FIELD SURVEY RESULTS

The following results do not include data collected between KP 425 to KP 450 which was lost due to a technological issue. All GPS points are provided in Appendix A, along with detailed information on each data point.

4.1. Weeds

The presence of weeds along the pipeline easement was similar to previous years (LES 2023, LES 2024). Some species have increased, especially kapok at the eastern end of the easement. There were very few instances of weeds previously recorded that could not be found on this survey. Several new areas of weed infestation were identified that were not recorded in 2024. Examples of weeds observed on the transitional rehabilitation assessment are shown in Figure .

Weed occurrences were typically in low density within the ROW and mostly the result of encroachment from adjacent pastoral land. This suggests that reestablishment of weeds is likely in most areas even if Jemena undertake actions to remove weeds from the easement. Parts of the ROW are used as access tracks for vehicles not associated with the NGP, this can also contribute to the spread of weed species along the ROW.

Introduced flora species identified on the rehabilitation assessment in 2025, their status in NT and Qld, and whether they are classified as a Weed of National Significance (WONS) are listed in Table 4. Declared weed species recorded included Noogoora burr and mesquite, which should be managed as a priority.

As noted in the 2023 and 2024 transitional rehabilitation assessments, an exception to the overall weed management performance is the persistence and continued spread of Kapok Bush (*Aerva javanica*) along the easternmost 40 km of the pipeline easement. The encroachment of Kapok Bush into adjacent areas was first observed in 2023, and its spread has further increased in 2024 and 2025. This indicates that the dense population within the easement is expanding both westward along the corridor and into surrounding land.

This is significant, as the RMP includes the performance indicator: *“No weed incursion or spread within the NGP footprint.”* The observed spread of kapok bush does not meet this criterion.

The patch of kapok identified in 2024 near a Cathodic Protection site at KP 566.4 has increased significantly. This patch was not recorded during the 2023 assessment and, given the absence of kapok bush near other ROW infrastructure, is likely to have been introduced via vehicle movement during ROW inspections. This constitutes another breach of the RMP performance indicator. The patch at KP 566.4 should be prioritised for treatment and removal to prevent further spread.

Refer to Appendix A for detail information on weed species and location.

Table 4. Introduced flora species observed during the survey.

| Common Name | Scientific Name | NT Weed Category* | Qld Weed Category** | WONS |
|-------------------|------------------------------|---|---------------------|------|
| Mesquite | <i>Prosopis</i> sp. | Class A and Class C | Category 3 | Yes |
| Prickly Acacia | <i>Vachellia farnesiana</i> | Class A and Class C | Other | No |
| Parkinsonia | <i>Parkinsonia aculeata</i> | Class B and Class C | Category 3 | No |
| Rubber Bush | <i>Calotropis procera</i> | Class B and Class C (south of 16°30' S latitude) | Other | No |
| Noogoora Burr | <i>Xanthium strumarium</i> | Class B and Class C | Other | No |
| Buffel Grass | <i>Cenchrus ciliaris</i> | Declared (unclassified) | Not Listed | No |
| Kapok Bush | <i>Aerva javanica</i> | Not Declared | Not Listed | No |
| Fleabane | <i>Conyza</i> sp. | Not Declared | Not Listed | No |
| Paddy Melon | <i>Cucumis myriocarpus</i> | Not Declared | Not Listed | No |
| Spiked Malvastrum | <i>Malvastrum americanum</i> | Not Declared | Not Listed | No |
| Verbena | <i>Verbena</i> sp. | Not Declared | Not Listed | No |

*NT weed categories: Class A - to be eradicated, Class B - growth and spread to be prevented, Class C - not to be introduced.

**Qld Weed categories: Category 3 - restricted (cannot be given away, sold or released into the environment).

Mesquite (*Prosopis* sp.)

Mesquite was observed at nine locations this year, three times more than in 2024. This increase in numbers is of concern as mesquite is a WONS, Class A and C in the NT and Category 3 weed in Qld. All sightings of mesquite not yet found in Queensland must be reported to Biosecurity Queensland within 24 hours of the sighting. Landholders, including Jemena, have an obligation to manage impacts of mesquite on their land.

Prickly Acacia (*Vachellia farnesiana*)

There were also an increased number of prickly acacias observed on the pipeline easement this year. Generally, they were in localised patches along the easement associated with drainage depressions or creek lines and frequently associated with other individuals in the adjacent pastoral land outside of the easement. Although the presence of the acacia may be associated with acacias in the surrounding lands, as a Class A listed species in the NT, efforts should be made to eradicate the plant. Disturbed soils associated with the pipeline may be providing prickly acacia with opportunities to become established.

Parkinsonia (*Parkinsonia aculeata*)

Parkinsonia was identified in one riparian area in 2025. There were two observations of the species in 2024, one could not be identified this year.

Rubber Bush (*Calotropis procera*)

Only one individual rubber bush was observed on the pipeline easement this year. Previously, it was observed at three locations.

Noogoora Burr (*Xanthium strumarium*)

The number of Noogoora burr patches observed on the pipeline easement has steadily increased over the previous couple of years and appears to be associated with pastoral activities. High density populations were observed in riparian corridors and areas of high cattle activity. There were also several observations of individual plants, often associated with gates and infrastructure (e.g. pipeline signs, monitoring poles).

Management actions should be taken to reduce its distribution, targeting areas around infrastructure and waterways. This is a high priority as the species is listed as a WONS. Low density isolated patches should be a priority to control and eliminate.

Buffel Grass (*Cenchrus ciliaris*)

Buffel grass was predominantly observed at both ends of the pipeline easement, which is consistent with expectations given the higher levels of vehicle traffic in these areas and the appropriate habitat. A section of buffel grass between KP XX and XX south of Barkly Homestead, appears to have been established by pastoral activities rather than as a direct result of pipeline operations. A dense patch of buffel grass recorded between KP 210 and KP 238 in the Northern Territory in 2023 and 2024 remains present, with evidence of minor spread to KP 246 observed in 2025. Isolated high-density patches were recorded in 2024 were also present this year in the railway corridor near KP 16 and also at KP 6 and 51. These isolated patches should be targeted to prevent further spread.

The recent declaration of Buffel grass as a weed under the *Weeds Management Act 2001* by the Northern Territory Government has increased the significance of managing these populations. The forthcoming classification will guide the specific control measures required.

Dense Buffel grass growth was also observed in the final 40 km of the eastern end of the pipeline easement—an area that also contains dense Kapok Bush. Unlike the Kapok Bush, this Buffel grass incursion is likely the result of spread from surrounding land, rather than direct disturbance associated with the pipeline.

Kapok Bush (*Aerva javanica*)

In a similar stretch (KP 222 to 238), kapok has become established, and it is well-established along the pipeline from KP 556 to 618. This is likely an impact of the pipeline and disturbed ground. Recent fires have reduced kapok presence KP 613 to 615 and it is a potential

management option. The increase of kapok since previous surveys (July 2023, July 2024) is an indicator that remediation actions should be implemented to prevent further spread. It is also recommended that kapok immediately adjacent to the easement, likely to have established because of activities associated with the pipeline, be removed. Fire reduces seed and adult plants, chemical control required during rapid growth stage of seedlings (following rainfall)

Fleabane (*Conyza* sp.)

One individual was observed on the pipeline easement; no observations of the species had been recorded prior. This species should be targeted to prevent it becoming established on the ROW.

Prickly Paddy Melon (*Cucumis myriocarpus*)

Three individual was observed on the pipeline easement; no observations of the species had been recorded prior. This species should be targeted to prevent it becoming established on the ROW.

Spiked Malvastrum (*Malvastrum americanum*)

Malvastrum is widespread across the Barkly Tablelands and is more likely associated with pastoral activities than with the pipeline itself. However, disturbance caused by pipeline construction and maintenance has likely facilitated its growth. Given its extensive distribution across pastoral lands, further spread along the pipeline corridor is likely. Eradication of this species is considered highly unlikely.

Verbena (*Verbena* sp.)

One individual was observed on the pipeline easement; no observations of the species had been recorded prior. This species should be targeted to prevent it becoming established on the ROW.

Weeds not Observed

Horehound (*Hyptis suaveolens*) was recorded within the ROW in 2023; however, it was not observed during the 2024 or 2025 surveys. This absence may be attributed to fire activity in areas where the species was previously recorded or due to suppression by competing groundstorey vegetation, particularly in years with higher vegetation cover. Although horehound has not been detected in the past two assessments, its presence in 2023 indicates that it remains a potential concern. Targeted monitoring following periods of increased rainfall is recommended to enable early detection and management of any re-emergence.




Figure 4-1. Introduced flora species observed during the survey displayed by weed classification. Refer to Table 4 for state and territory categories.




Figure 4-2. Images from the transitional rehabilitation assessment survey: a) Kapok bush along vehicle road on ROW, b) Spiky acacia, c) Kapok bush and erosion d) Mesquite e) Noogoora burr at base of infrastructure, likely from cattle scratching, f) multiple weed species including malvastrum, Noogoora burr and spiky acacia

4.2. Land Stability

4.2.1. Erosion

Erosion was recorded at numerous locations along the easement; however, approximately 60% of these instances were classified as minor, and only 5% were considered moderate to severe. The breakdown of erosion severity is as follows:

Level 1: Significant issues requiring remediation – 2%

Level 2: Moderate issues with potential to become significant, requiring remediation – 3%

Level 3: Moderate issues requiring remediation – 24%

Level 4: Minor issues requiring monitoring – 31%

Level 5: Very minor issues requiring monitoring – 32%

In addition, erosion directly attributed to vehicle activity accounted for approximately 9% of the records.

Remediation work has seen instances of erosion decrease along the length of the pipeline easement since it was last surveyed in 2024 (Table 5).

Table 5. Number of erosion instances in 2024 vs 2025.

| Erosion classification | Number of Observations in 2024 | Number of Observations in 2025 |
|------------------------|--------------------------------|--------------------------------|
| Level 1 | 7 | 4 |
| Level 2 | 28 | 7 |
| Level 3 | 66 | 51 |
| Level 4 | 270 | 66 |
| Level 5 | 19 | 68 |

As noted in previous surveys (LES 2023, LES 2024), the majority of erosion was confined to the access track within the ROW, where limited vegetation cover increased susceptibility to erosion. Sheet erosion was the most common form.

Grading activities are likely to increase susceptibility to erosion both in areas where berms had been removed, and in areas where grading has formed windrows. Windrows have the potential to cause altered water flow and encourage erosion by preventing water from leaving the easement.

Gully erosion was observed primarily in areas adjacent to or along drainage lines. In some areas, erosion was caused or exacerbated by cattle movement along the access track.

Along the ROW there were sections where the surface of the easement was lower than the surrounding landscape. These sections are likely to alter the natural waterflow in the area and cause water to pool and flow down the easement. Erosion was found on the edge of these low areas extending into the easement due to the difference in ground level.

Examples of varying degrees of erosion observed in the transitional rehabilitation assessment are shown in Figure and Figure .

All Level 1 and Level 2 erosion should be prioritised for remediation through filling and the installation of erosion control berms. Where earthworks machinery is already operating in the vicinity, opportunistic rehabilitation of Level 3 erosion should also be undertaken. Level 4 and Level 5 erosion can generally be managed through the installation of erosion control berms alone. Management of erosion near water crossing should also be prioritised. Vehicles should be encouraged to stay on the access track to reduce vehicle erosion across other areas of the ROW.

Similar to the 2024 transitional rehabilitation assessment, high vegetation cover across significant portions of the ROW made accurate erosion assessment difficult in those areas. As a result, the extent of erosion may be underreported.

Locations of erosion issues are presented in Appendix A.




Figure 4-3. Locations of erosion observed on the NGP ROW in 2025.




Figure 4-4. Images from the transitional rehabilitation assessment survey: a) Windrow that needs to be brought in, b) grading creating height difference c) overgraded section with berms removed, windrows built up and sheet erosion (level 5).




Figure 4-5. Images from the transitional rehabilitation assessment survey: a) erosion at a creek crossing, b) level 4 erosion, c) level 3 erosion, d) level 1 erosion, e) level 2 erosion.

4.2.2. Compromised Berms

Comparison of the number of compromised berms in 2025 to previous years is difficult, as grading activities on the western end of the pipeline have resulted in the complete removal of multiple berms. In these areas, multiple series of shallow berms must be constructed to prevent erosion on the ROW.

Of the berms that remain, 42 have been compromised. For comparison, in 2024 the number of compromised berms increased to 65, compared to a total of 28 in 2023. In 2024, compromised berms were most prevalent on the western end of the ROW, where many of the berms have now been completely removed.

Damage was most often due to water erosion, resulting in erosion channels forming through the berms or the berms being washed out. There were several occurrences of water flowing around the ends of berms and back onto the ROW, rather than diverting outwards into adjacent land. This was often due to berms not extending far enough at the edges of the ROW.

Cattle tracking also caused erosion of berms in some instances, along with vehicle activity along the access track of the ROW. Several berms were ineffective due to their orientation on the ROW, where their construction did not follow the natural lay of the land, causing water to flow directly back onto the ROW.

Many of the berms would be more effective if they extended beyond the disturbed area of the ROW easement, allowing water to be diverted and dispersed onto adjacent undisturbed land. In some cases, this may not have been possible due to heritage buffers, which restricted berm construction to within the ROW. Some berms that do not extend beyond the easement fail to fully divert water off the ROW, allowing it to flow around the ends of the berm and continue channelling downslope, increasing the risk of erosion.

Several of the berms on the ROW were not appropriate in height and width. Rather than one tall narrow berm, which can impede vehicle and machinery movement, series of wide, shallow berms would be most effective.

All compromised berms should be repaired or reinstated promptly. Locations of observed compromised berms along the NGP ROW and proposed berm locations are presented in Figure . Refer to Appendix A for locations and recommendations regarding compromised berms and additional berms.




Figure 4-6. Locations of compromised berms observed on the NGP ROW in 2025.




Figure 4-7. Images from the transitional rehabilitation assessment survey: a) berm has been removed in recent grading works b) compromised berm.

4.2.3. Subsidence

Subsidence issues were recorded at 17 locations along the ROW in 2025, a decrease from 57 instances recorded in 2024. This reduction is likely due to both a genuine decline in occurrences through remediation works and potentially influenced by differences in assessment between individual assessors.

Most of the observed issues were caused by water channelling and erosion across the pipeline, with some attributed to cattle and vehicle activity.

There were few instances of significant or moderate subsidence, most of which occurred in the Barkly Tablelands. It is recommended that all significant or moderate subsidence areas be remediated through filling, while minor subsidence should be monitored over time.

Locations of observed subsidence along the NGP ROW are presented in Figure . Refer to Appendix A for locations and recommended actions.




Figure 4-8. Locations of observed subsidence along the NGP ROW in 2025.




Figure 4-9. Images from the transitional rehabilitation assessment survey: a) level 2 subsidence, b) level 4 subsidence.

4.3. Land Stability Remediation

At the time of the transitional rehabilitation assessment in June 2025, grading and vegetation clearing were underway at the western end of the ROW. Similar activities were also occurring in this area during the 2024 assessment.

Much of the erosion and subsidence observed during the 2023 and 2024 assessments has been remediated (Figure).

However, as discussed above, some of the remediation work on the ROW has created new issues that now require further attention. In particular, grading has resulted in the formation of windrows, the removal of berms, and the accumulation of soil and plant material piles on the side of the ROW that need to be redistributed. In some locations, valuable topsoil has been pushed off the ROW, which is impeding revegetation. Locations of works required are shown in Figure



Figure 4-10. Image from the transitional rehabilitation assessment survey: remediated erosion.




Figure 4-11. Location of additional remediation works required on the ROW.

4.4. Revegetation/Overgrowth

Revegetation

Vegetation cover across the ROW at the time of assessment was generally high. Extensive overstorey growth across significant stretches of the easement indicates that rehabilitation following construction is progressing, with the majority of the ROW assessed as exhibiting excellent revegetation. Notably, spinifex species were observed in areas previous assessments had noted the species had not yet reestablished.

This regrowth is likely supported by above-average rainfall during 2023 and 2024, and recent rainfall prior to the 2025 assessment. Most of the ROW had high species richness and ground cover; however, in some areas, thick overstorey vegetation was limiting the development of ground cover.

Vegetation extent across the ROW observed were as follows:

- Vegetation Level 1 – 6%
- Vegetation Level 2 – 15%
- Vegetation Level 3 – 19%
- Vegetation Level 4 – 19%
- Vegetation Level 5 – 41%

It should be noted that the vegetation on the ROW does not always reflect species composition and density in the surrounds. Often, species that thrive in disturbed soils are more abundant in the ROW. This is true for all land systems but more pronounced in some than others.

Some small areas along the ROW showed little to no regrowth, typically where topsoil had been removed due to erosion, grading, or the creation of laydown areas during construction. These areas are unlikely to regenerate without intervention. The addition of topsoil, ideally sourced from nearby cleared areas where stockpiles remain, is recommended to aid recovery. The addition of topsoil will be needed and ideally, be similar to the surrounding soil. It was observed in areas which had been cleared, topsoil had been pushed to the side in piles, and this soil would be ideal to rehabilitate nearby erosion and topsoil loss (refer to Section 7.3).

Due to the excessive overstorey growth and land stability issues, grading of the ROW had begun from the western end of the pipeline to approximately 88.6 km. This had remedied some erosion but also removed almost all vegetation from a 20 m width of the ROW.

As noted in both the 2023 and 2024 reports, the easternmost 40 km of the ROW remains heavily impacted by weed growth. This continues to limit native vegetation recovery. Targeted weed control in this area will assist in improving rehabilitation outcomes.

The ROW between KP 356 - KP 526 and KP 535 - KP 560 crossed the Barkley, Georgina, Wonardo, Austral, Wonorah-Barkley and Kalalla land systems of the Barkley Tablelands. This

section is characterised by open grass plans with very little woody vegetation growth. No overstorey growth was observed along the ROW and the ground cover does not obstruct vision or impact on pipeline infrastructure, therefore can and should be maintained.

Overgrowth

Some sections of the ROW experienced significant overstorey growth, particularly between KP 251 and KP 296. These areas, situated within the Wonorah and Yelvertoft land systems, are dominated by stony quartz soils and support woody shrubs such as *Acacia hilliana*. Although these shrubs do not obstruct access, their woody structure qualifies them as overstorey vegetation, which may compromise land stability assessments and pose risks to pipeline integrity.

Dense overstorey vegetation was also observed across multiple other sections of the ROW, impeding access and obscuring signage and access tracks. To meet AS 2885 minimum vegetation management requirements, this overgrowth requires removal.

Grading works had commenced at the western end of the pipeline, near the Phillip Creek Compressor Station, extending to approximately 88.6 km. While this temporarily impacts ground cover, the existing vegetation has demonstrated resilience and is likely to re-establish under suitable conditions.

Overgrowth was reduced in 2025 compared to 2024, as targeted clearing activities were conducted across several sections. Cleared vegetation and topsoil were pushed into piles alongside the ROW. These piles are high in nutrients and contain viable seed banks, making them suitable for redistribution across degraded areas—provided fauna safety is considered during the process.

Regular maintenance, including slashing and overstorey suppression, will be necessary to prevent future re-establishment. Continued removal of overstorey vegetation is essential for pipeline integrity, access, and safety. Clearing activities should also be used to address land stability issues and to install or repair berms and other erosion control structures where needed.

Overgrowth along the NGP ROW is mapped in Figure , with recommended actions discussed in Section 7.3.




Figure 4-12. Overgrowth along the NGP ROW observed in 2025.




Figure 4-13. Images from the transitional rehabilitation assessment survey: a) level 5 vegetation, shrubs require clearing, landholder maintains road clear as effective fire break, b) level 2 vegetation, lack of topsoil impeding revegetation, c) and d) level 5 vegetation, shrubs require removal.




Figure 4-14. Images from the transitional rehabilitation assessment survey: a) level 5 vegetation with no shrubs, b) level 1 vegetation caused by grading, c) cattle tracks through vegetation, d) level 5 vegetation in comparison to surrounds, e) level 5 vegetation with some shrubs that will require clearing, f) level 5 vegetation with whitewood in easement, high priority to clear as growing over pipeline.

4.5. Infrastructure

Throughout the survey, the condition of signage poles and monitoring poles was noted. There were many occasions where signage was not visible due to overgrowth.

There were many pipeline signage poles that were damaged, burned, had fallen over or been knocked over. Often damaged signs were on the pastoral land between KP 356 and KP 560, suggesting cattle had used them as scratching poles in a landscape with very few trees (Figure). This year there were multiple burned signs towards Mount Isa from recent fires.

There were only two observations of damaged monitoring poles which had fallen over or been knocked over by cattle. There were exposed wires at the base and repairing them should be a high priority.

There was dense vegetation inside the fencing at Main Line Valve 3. This was reported to Jemena field staff at the completion of the field assessment (Figure 4-17).

Locations of damaged infrastructure are shown in Figure and a summary of infrastructure issues are included in Appendix A.




Figure 4-15. Locations of damaged infrastructure observed on the ROW in 2025.



Figure 4-16. Images from the transitional rehabilitation assessment survey: a) fallen sign, b) damaged pole with exposed wires, c) burned sign, d) cattle using sign as scratching post.



Figure 4-17. Vegetation posing a potential fire risk inside the fencing at Main Line Valve 3.

4.6. Plains Death Adder Habitat Survey

This section pertains only to the land systems surveyed for plains death adder habitat. Additional surveys are required in the future targeting all remaining land systems that intersect with the NGP.

Criteria 4.3.1. (a) greater than or equal to 70 % of native ground cover species richness

The transitional rehabilitation criteria requires that at least 70% of flora species present in the representative adjacent habitat should be present in the ROW. Whilst there was good quality vegetation and coverage present on the ROW at all sites surveyed, the composition of species met this 70% threshold at five sites, two in the Kalalla land system and one site each in of the Barkly, Georgina and Wonardo land systems (Table 6).

Flora species observed in quadrats at all sites are listed in Table 6.

Table 6. Summary of plains death adder habitat survey data.

| Site | Land System | % Species Present on ROW that are Present off ROW |
|------|-------------|---|
| MG01 | Barkly | 60% |
| MG02 | Barkly | 71.4% |
| MG03 | Georgina | 75% |
| MG04 | Austral | 64.7% |
| MG05 | Wonardo | 37.5% |
| MG06 | Austral | 61.5% |
| MG07 | Austral | 50% |
| MG08 | Austral | 66.7% |
| MG09 | Wonardo | 70% |
| MG10 | Barkly | 55.6% |
| MG11 | Wonardo | 57.1% |
| MG12 | Kalalla | 80% |
| MG13 | Kalalla | 70.6% |
| MG14 | Kalalla | 59.1% |

Table 7. List of all flora species recorded in quadrats.

| | | |
|--------------------------------|---|-----------------------------------|
| <i>Abelmoschus ficulneus</i> | <i>Euphorbia mitchelliana</i> | <i>Pluchea ferdinandi-mulleri</i> |
| <i>Abutilon hannii</i> | <i>Euphorbia tannensis</i> | <i>Polymeria longifolia</i> |
| <i>Acacia nilotica</i> | <i>Evolvulus alsinoides</i> | <i>Portulaca digyna</i> |
| <i>Acacia victoriae</i> | <i>Evolvulus alsinoides</i> var. <i>villosicalyx ooststr</i> | <i>Portulaca filifolia</i> |
| <i>Alternanthera nodiflora</i> | <i>Fimbristylus</i> sp. | <i>Portulaca oleracea</i> |
| <i>Alysicarpus muelleri</i> | <i>Flaveria australascia</i> | <i>Prosopis pallida</i> |
| <i>Aristada holathera</i> | <i>Glycine falcata</i> | <i>Ptilotus exaltatus</i> |
| <i>Aristida latifolia</i> | <i>Gomphrena breviflora</i> | <i>Ptilotus spicatus</i> |
| <i>Aristida pruinosa</i> | <i>Gomphrena conica</i> | <i>Rhynchosia minima</i> |
| <i>Astrebla elymoides</i> | <i>Goodenia nigrescens</i> | <i>Rostellularia adscendens</i> |
| <i>Astrebla pectinata</i> | <i>Goodenia ramelii</i> | <i>Salsola tragus</i> |
| <i>Astrebla squarrosa</i> | <i>Goodenia strangfordii</i> | <i>Schizachyrium fragile</i> |
| <i>Brachyscome dentata</i> | <i>Gossypium sturtoanum</i> | <i>Sclerolaena bicornis</i> |
| <i>Chloris pectinata</i> | <i>Haloragis aspera</i> | <i>Sclerolaena cornishiana</i> |
| <i>Chrysopogon fallax</i> | <i>Hibiscus trionum</i> | <i>Senna planitiicola</i> |
| <i>Cleome viscosa</i> | <i>Ipomoea costata</i> | <i>Sida fibulifera</i> |
| <i>Cucumis melo</i> | <i>Ipomoea diamantinensis</i> | <i>Sida filiformis</i> |
| <i>Cullen cinereum</i> | <i>Ipomoea Lonchophylla</i> | <i>Sida laevis</i> = |
| <i>Cullen pustulatum</i> | <i>Ipomoea muelleri</i> | <i>Sida</i> sp. Walhallow station |
| <i>Cynodon dactylon</i> | <i>Iseilema fragile</i> | <i>Sida trichopeda</i> |
| <i>Cyperus gilesii</i> | <i>Iseilema membranaceum</i> | <i>Solanum succosum</i> |
| <i>Dactyloctenium radulans</i> | <i>Iseilema vagiflorum</i> | <i>Spermacoc brachystone</i> |
| <i>Desmodium campylocaulon</i> | <i>Malvastrum americanum</i> | <i>Stemodia</i> sp. Tanamai |
| <i>Dicanthium sericeum</i> | <i>Neptunia dimorphantha</i> | <i>Streptoglossa adscendens</i> |
| <i>Digitaria coenicola</i> | <i>Neptunia monosperma</i> | <i>Streptoglossa bubakii</i> |
| <i>Eragrostis eriopoda</i> | <i>Oleria ciliata</i> | <i>Stylidurum desertora</i> |
| <i>Eragrostis tenellula</i> | <i>Oleria ferresii</i> | <i>Trichodesma zeylanicum</i> |
| <i>Eriachne benthamii</i> | <i>Oleria stuartii</i> | <i>Triraphis mollis</i> |
| <i>Eulalia aurea</i> | <i>Operculina aequiseipala</i> | <i>Vicia Sativa</i> |
| <i>Euphorbia australis</i> | <i>Oryza australiensis</i> | <i>Vigna lanceolata</i> |
| <i>Euphorbia coghlanii</i> | <i>panicum decompositum</i> | <i>Yakirra asutraliensis</i> |
| <i>Euphorbia drummondii</i> | <i>Phyllanthus maderaspatensis</i> | |

Criteria 4.3.1. (b) greater than or equal to the total per cent of ground cover

Vegetation cover, leaf litter, bare ground and rocks were recorded every metre along a 100 m transect both on and off the ROW at each site. The percentage of vegetation cover is detailed in Table 8. Refer to Figure 4-18 Figure 4-19 and for examples of vegetation cover on the ROW compared to vegetation cover off the ROW.

Table 8. Percentage of vegetation cover.

| Site | Veg Cover on ROW | Veg Cover off ROW | Difference |
|------|------------------|-------------------|------------|
| MG01 | 41% | 50% | 9% |
| MG02 | 58% | 64% | 6% |
| MG03 | 60% | 60% | 0% |
| MG04 | 53% | 55% | 2% |
| MG05 | 52% | 38% | -14% |
| MG06 | 46% | 39% | -7% |
| MG07 | 65% | 51% | -14% |
| MG08 | 39% | 57% | 18% |
| MG09 | 61% | 64% | 3% |
| MG10 | 30% | 30% | 0% |
| MG11 | 72% | 67% | -5% |
| MG12 | 55% | 45% | -10% |
| MG13 | 61% | 67% | 6% |
| MG14 | 46% | 70% | 24% |

Criteria 4.3.1. (c) less than or equal to the per cent species richness of declared plant pest species

There was only one observation of WONS prickly acacia, this was in a quadrat and not on a transect, thus unquantifiable. There were no other declared weeds on the ROW.

Criteria 4.3.1. (d) where the adjacent land use contains, or the pre-clearing land use contained, one or more regional ecosystem(s), then at least one regional ecosystem(s) from the same broad vegetation group, and with the equivalent biodiversity status or a biodiversity status with a high conservation value as any of the regional ecosystem(s) in either the adjacent land or pre-disturbed land, must be present.

The number of cracks and holes on the ROW compared to off the ROW was deemed to be representative at most sites. See Figure 4-20/Figure 4-21 for examples of cracks and holes formed on the ROW.

Table 9. Cracks and holes recorded on and off the ROW.

| Site | Land System | Cracks off ROW | Cracks on ROW | Holes off ROW | Holes on ROW |
|------|-------------|----------------|---------------|---------------|--------------|
| MG01 | Barkly | 8 | 12 | 14 | 24 |

| | | | | | |
|-------------|----------|----|----|----|----|
| MG02 | Barkly | 11 | 9 | 28 | 13 |
| MG03 | Georgina | 15 | 1 | 17 | 1 |
| MG04 | Austral | 9 | 9 | 18 | 20 |
| MG05 | Wonardo | 16 | 1 | 6 | 6 |
| MG06 | Austral | 0 | 1 | 44 | 45 |
| MG07 | Austral | 2 | 2 | 33 | 17 |
| MG08 | Austral | 2 | 4 | 21 | 29 |
| MG09 | Wonardo | 5 | 4 | 37 | 11 |
| MG10 | Barkly | 0 | 0 | 0 | 2 |
| MG11 | Wonardo | 3 | 0 | 1 | 5 |
| MG12 | Kalalla | 35 | 18 | 3 | 0 |
| MG13 | Kalalla | 13 | 1 | 1 | 2 |
| MG14 | Kalalla | 39 | 34 | 1 | 1 |

Whilst there has been good progress towards rehabilitation, RMP criteria has not yet been met.



Figure 4-18. Vegetation on the ROW similar to vegetation off the ROW but not yet meeting transition criteria.



Figure 4-19. Images from assessment survey. Mitchell grasses recovering well in general. (a) KP 400 vegetation cover on the ROW representative of vegetation off the ROW, (b) cattle tracks following the ROW, impacting vegetation cover and (c) less vegetation cover on the ROW compared to off the ROW.



Figure 4-20. Blue tongue lizard using crack formed on the ROW.



Figure 4-21. Examples of cracks and holes on the ROW.

5. ASSESSMENT OF TRANSITIONAL COMPLETION CRITERIA

As the RMP review has not been finalised, the transitional completion criteria used in this assessment are from the original RMP.

The following criteria are used to assess the transitional rehabilitation status of disturbed areas.

Significantly disturbed areas that are no longer required for operational purposes, must be transitionally rehabilitated within 12 months (unless exceptional circumstance in the area to be rehabilitated (e.g. flood event) prevents this timeframe being met) and be maintained to meet the following acceptance criteria:

- a) *Disturbed areas are:*
 - i. *a stable landform*
 - ii. *re-profiled to contours consistent with the surrounding landform*
- b) *Surface drainage lines are re-established;*
- c) *Topsoil is reinstated in disturbed areas; and*
- d) *Either:*
 - i. *Ground cover, that is not a declared pest species, is growing in disturbed areas; or*
 - ii. *an alternative soil stabilisation methodology that achieves effective stabilisation is implemented and maintained in disturbed areas.*

No less than 791 ha of suitable Plains Death Adder habitat is rehabilitated within 5 years of completion of construction.

Table 10 summarises the results of the assessment of each transitional rehabilitation criteria. This table reports on the fifth year of the 5-year transitional rehabilitation phase.

Table 10. Assessment of transitional rehabilitation criteria.

| Criteria | Conclusion/Recommendations |
|--|--|
| Disturbed areas are a stable landform within 12 months. | Incomplete. There is a significant portion which meets this criterion. However, there were areas of erosion, subsidence, and ineffective and deteriorating berms observed at various locations throughout the ROW. These conditions are predominately minor; however, management action is required to achieve a stable landform along the pipeline in areas identified as having moderate to significant land stability issues. Recommendations are provided in Section 7. |
| Disturbed areas are re-profiled to contours consistent with the surrounding landform within 12 months. | This criterion was met in the 2023, however, areas of the ROW that had become lower than the surrounding landscape were noted in both 2024 and 2025. This lowering was most likely a result of grading over the ROW and/or repeated vehicle access on the ROW, and due to removal of material through sheet flow erosion. These areas were uncommon and sporadic over the easement; however, this increases the risk of erosion and pooling of water. Actions should be taken to raise the level of the ROW erosion control berms as |

| | |
|--|--|
| | appropriate in these areas and monitoring should occur to ensure adverse effects do not occur and the issue does not progress. |
| Surface drainage lines are re-established within 12 months. | Complete, but with minor exceptions. Re-establishment was completed during the project's reinstatement phase. This criterion has been met; however, it is recommended that monitoring and water flow management be continued to reduce any negative effects where drainage depressions cross or coincide with the ROW. |
| Topsoil is re-instated and maintained in all disturbed areas. | This criterion was undertaken during the projects' reinstatement phase, however, the action of erosion and to a lesser extent grading and clearing of the ROW has reduced or removed topsoil from some areas. The recommendation is that topsoil be replaced in these areas as an action of remediating erosion, plus soil stabilisation methods, such as berms, and encouraging vegetation be utilised to reduce the risk of further loss. |
| Ground cover which is not a declared species is growing in disturbed areas within 12 months of the completion of construction activities and maintained. | Incomplete. Overall, the 622 km long ROW is revegetating well and mostly meets the transitional rehabilitation criteria. Removal of ground cover is currently necessary to remove the undesirable overstorey, however, ground cover should recover and be managed in the future by slashing with a minimum ground clearance between 150 and 300 mm. Further recommendations are provided in Section 7. |
| An alternative soil stabilisation methodology that achieves effective stabilisation is implemented and maintained in disturbed areas. | Incomplete. In areas that are currently not stabilised with sufficient ground cover, erosion control berms are in place along sections of the ROW, however, some have been cleared with grading while others have been compromised, and some areas require additional berms. Recommendations are provided in Section 7. |
| No weed incursion or spread within the NGP footprint. | <p>Incomplete. Occurrences of declared weed species within the ROW are limited and are predominately a result of encroachment from adjacent pastoral land. There are some instances of declared weed species within the ROW that require management, including Noogoora burr and mesquite. To be effective, cooperative control with the adjacent landholders would be required and control should take place before seed set and focus on upstream and/or upwind weed populations.</p> <p>The largest weed encroachments within the ROW occur in the easternmost 40 km. Dense to moderately dense populations of kapok bush have been established within the ROW in large areas. Kapok bush is not a declared weed species however management is recommended to remediate spread along the ROW and into adjacent land. Refer to Section 7 for recommendations. The population of kapok bush at KP 556.3 is likely the result of pipeline activities and should be a priority to manage.</p> |
| No less than 791 ha of suitable Plains Death Adder habitat is rehabilitated within 5 years of completion of construction. | Incomplete. Habitat is showing increased rehabilitation. Cracks along the appropriate habitat are forming and vegetation cover is high creating a habitat appropriate for hunting and temporary shelter. More time is required for vegetation on ROW to become representative of vegetation off the ROW. |

The transitional rehabilitation of the NGP ROW continues to advance and is estimated to be over 85% complete. Required clearing of the overstorey on the ROW will likely remove the ground cover from highly rehabilitated areas, leading to an interim reduction in rehabilitation which will need to be monitored for land stability until ground cover is reestablished. This will be a good opportunity to remediate land stability issues. After which, management efforts will be important to enable quick recovery and high rehabilitation success.

6. RISKS TO REHABILITATION OBJECTIVES

The management actions detailed in Section 7 have been identified to meet the respective completion criteria. However, following the implementation of management actions, some events or circumstances may impede the attainment of completion criteria. The following events/circumstances have been identified in the RMP as posing a risk to achieving rehabilitation objectives:

- **Increase in the diversity of weed species.** Even after weed hygiene is undertaken (particularly vehicle hygiene and weed inspections prior to transport to site), there is a chance that weed species not currently present in within the Project footprint may be brought to site. New weed introduction poses a risk to the land returning to a comparable pre-disturbance state and the habitat for plains death adder being rehabilitated.
- **Increase in weed cover.** Increase in weed cover could occur due to opportunistic growth into disturbed areas where there are existing weeds present. Increase in weed cover could prevent or delay the establishment of native ground cover species and/or suppress ground cover species richness. This would hinder suitable habitat for the Plains Death Adder returning, and the return of the land to comparable pre-disturbance state.
- **Erosion at watercourse crossings.** Watercourse crossings are the most likely location for erosion to occur. Without management actions, watercourse crossings are expected to erode due to river flow. Erosion of this nature poses a risk to the objective of returning the land to a comparable pre-disturbance state, and (in areas) would prevent the successful rehabilitation of suitable plains death adder habitat.
- **Extreme weather event which negatively impacts rehabilitation.** As construction is occurring in the dry season, it is unlikely that an extreme weather event (particularly flooding rain) will occur prior to reinstatement, however, such an event could occur before rehabilitation is complete. An extreme weather event could wash away rehabilitated areas (both land and vegetation) and negatively impact on landform in general and specifically plains death adder habitat. Alternatively, a protracted drought could lead to rehabilitation objectives not being met.
- **Stock or native fauna activity impacting rehabilitation.** As the land is currently used for grazing stock and supports native fauna, rehabilitation could be impacted by stock and/or fauna grazing. This is most likely to occur around water points (troughs, dams etc). This activity could suppress the regeneration of native species, and in turn, the rehabilitation of the land to its pre-disturbance condition.
- **Unplanned/uncontrolled fire.** Construction activities during the dry season, particularly the use of heavy machinery for vegetation clearing, are a possible source

of wildfire ignition. Although heavy machinery will be used predominately in clearing and on the cleared ROW, a fire that spreads into reinstated areas could negatively impact rehabilitation success through burning new growth.

A number of these risks to rehabilitation have occurred over the past three years of transitional rehabilitation which pose a risk to achieving rehabilitation objectives, which are summarised in Table 11.

Table 11. Risks to transitional rehabilitation completion.

| Risk | Event or circumstance |
|--|--|
| Increase in weed cover | Kapok bush does well in disturbed soils, the combination of disturbed soils and vehicle traffic on multiple sections of the pipeline has caused the spread of this species. Significant rainfall events during the 2023 and 2024 summer periods resulted in increased revegetation along the pipeline easement, which also assisted in the spread and proliferation of weed species such as Noogoora burr and kapok bush. |
| Extreme weather event that negatively impacts rehabilitation | The NGP project area has experienced two years of significant rainfall events, a total of 600-700 mm per year in 2023 and 2024. This year alone Tennant Creek recorded over 1,000 mm within just 6 months, and Mt Isa and Camooweal 600-700 mm in the same period. Significant rainfall events such as these increase the risk of erosion, remove topsoil and negatively impact the progress of rehabilitation. |
| Stock or native fauna activity impacting rehabilitation. | The majority of the NGP project area is situated within pastoral land used for grazing stock. Stock activity around watering points and cattle tracks along the ROW are obvious and have contributed to erosion in some areas and have likely contributed to the spread of weeds, such as Noogoora burr. Disturbance from cattle in high-activity locations has also likely suppressed the regeneration of native vegetation. |
| Unplanned/ uncontrolled fire | Fire occurrences between September and October 2023 have affected a large area of the NGP project area. Significant rainfall events resulting in an increase of vegetation along the ROW likely fuelled fires caused by lightning strikes. This has negatively impacted rehabilitation efforts by burning new growth and removing organic material that naturally stabilises the soil, therefore becoming more prone to erosion. |

7. CONCLUSION AND RECOMMENDATIONS

The sixth transitional rehabilitation survey of the Northern Gas Pipeline undertaken in June 2025 found the condition of the ROW to have improved compared to the 2024 surveys in some categories including land erosion but to have worsened in other aspects i.e. weed management. Generally, the condition of the disturbed areas present on the ROW have remained relatively stable and shows good to excellent rehabilitation over the ROW.

7.1. Weeds

The presence of weeds was still evident in the ROW, however, management to remove mesquite has been somewhat effective. The mesquite trees identified in this assessment were adjacent to the cleared area of the ROW and minimal effort would be required to remove these. They appeared to be isolated individual trees; therefore, it is encouraged to remove the issue of this Weed of National Significance from the easement as a priority. Cooperative discussions with the adjoining landholder provides opportunity to remove adjacent seed sources.

Noogoora burr was observed in high density along riparian corridors, often however, the weed was also located just outside the easement making management of these populations difficult without the cooperation of adjacent landowners. It is recommended that initial efforts are focussed on the small, isolated populations of Noogoora burr along the ROW which most likely occur due to cattle transporting seeds to these areas. This initial management effort would help reduce the further spread of this weed.

Weed management should also target the kapok bush population in the vicinity of KP 566 which has increased since the 2024 survey. This population is highly likely a result of pipeline management vehicles transporting seeds to this area and is therefore the responsibility of Jemena to remove as the seed has already begun to spread. Vehicle hygiene practices should ensure this does not happen in the future. The high density of kapok bush in the eastern 40 km of the pipeline was discussed in the both the 2023 and 2024 reports and has since continued to spread off the ROW and into the surrounding landscape. The RMP performance indicator for transitional rehabilitation of '*No weed incursion or spread within the NGP footprint*' is affected by the above-mentioned kapok bush populations and therefore efforts should be made to control these populations as soon as possible.

A targeted survey to map large infestations of weeds and treat the isolated populations may be an effective way of managing the weed populations on the ROW. This survey could also remove the small populations of Noogoora burr, mesquite, kapok bush and rubber bush identified during the 2025 survey.

Recommendations regarding management of non-declared weed species are the same as advice provided in 2024 (LES). High density populations should be targeted to prevent further spread along the easement and into adjacent land. In particular, the populations of kapok bush

near KP 566, and the eastern most 40 km stretch of the ROW, have increased in size and continue to spread into the surrounding landscape.

Ongoing management and working in conjunction with local landholders is required to reduce the spread of weed species along the easement and into surrounding lands.

The following actions are recommended to meet the transitional rehabilitation criteria:

- Prioritise management of all instances of declared weeds.
- Consider working with adjacent landholders for long term management of weed encroachment into the ROW. Management should take place before seed set and focus on upstream or upwind weed populations.
- Management actions for non-declared weeds should focus on areas of high infestation, particularly the spreading populations of kapok bush in the far eastern portion of the ROW and the Cathodic Protection site at KP 566.4
- Future monitoring should reinspect all weed records to ensure control has been effective and weeds have not spread.

7.2. Land Stability

Much of the land stability issues, erosion and subsidence, documented in the 2024 assessment appeared to have been remediated by the earthworks being undertaken in the western half of the NGP.

Reinstating erosion control berms in areas where they have been removed by grading and remediation works is a high priority. Windrows formed by grading and areas where grading has caused the ROW to become lower than the surrounding landscape, the risk of erosion is increased because they effect the flow of water. These issues should be addressed where required and machinery operators responsible for the maintenance of the ROW should be alerted to the importance of eliminating these issues to promote effective water flow.

Piles of soil and plant material accumulated from the clearing was observed along the edges of the ROW. These should be redistributed on the ROW and is ideal to use to fill in any subsidence and erosion in the vicinity of the soil or to construct shallow berms for runoff control. If this soil contains woody vegetation, it should not be distributed on the vehicle access section of the easement to reduce the risk of vehicle damage. As these piles of vegetation have been stockpiled for a lengthy duration, the APGA CoEP requires a suitably qualified fauna spotter/catcher to check the stockpile and catch and relocate any fauna inhabiting the vegetation and soil, prior to redistributing on the ROW.

The following actions are recommended to meet the land stability transitional rehabilitation criteria:

- Remediate all Level 1 and 2 land stability issues as a priority.
- Remediate Level 3 moderate land stability issues.
- Monitor Level 4 and 5 minor land stability issues.

- Construct additional erosion control berms as required upslope of areas where erosion or subsidence is developing due to water channelling along ROW.
- Where appropriate, back-fill and level subsidence surrounding landscape level.
- Where appropriate, fill and level erosion occurrences to prevent further advancement and encourage vegetation to establish. Eroded sediment from the downslope could be used where available.
- Where appropriate, return ROW easement to the surrounding landscape level.
- Remove windrows.
- Repair compromised berms, with some requiring extension, if possible, to effectively remediate erosion issues.
- Re-build berms after vegetation clearance and in future, alter clearance methods to keep berms intact (i.e. slashing).
- Ensure berms are oriented correctly to ensure desired water management.

7.3. Revegetation and Overgrowth

The level of revegetation was high along the ROW with most sections being assessed as having good ground cover with a high species richness. There were only a few sections of the easement where vegetation was observed to be slow to reestablish.

It is widely accepted that rehabilitation best practice is to allow the environment to recover naturally. This can lead to a more robust and resilient environment. In areas where topsoil is still present, it is recommended that these areas be left to revegetate naturally with continued monitoring for weeds and erosion.

Some areas of low revegetation are likely due to a lack of topsoil, lost through overzealous grading and erosion. The topsoil needs to be replaced, ideally with similar soil from graded areas nearby. Erosion control will be important in these areas to keep the replaced topsoil in position. However, considering the regrowth in adjacent areas in the ROW, suggests if this is done effectively, revegetation will occur quickly.

While the revegetation is high in most areas, most of this revegetation consists of an overstory. The Australian standards for high pressure pipeline systems, AS 2885, states that vegetation within the pipeline corridor shall be managed to:

- a) Maintain line of sight between pipeline markers;*
- b) Maintain access and line of site for third party detection and pipeline patrols;*
- c) Minimise the risk of roots damaging the pipeline coating; and*
- d) Minimise the risk of damage to above-ground facilities due to radiant heat in the event of a bushfire.*

In addition, the Group Gas Operational Environmental Management Plan (GAS-999-PA-EV-002) (2021) recommends '*Regrowth vegetation on the pipeline easement shall be maintained to ensure root systems do not create a safety risk to the pipeline*'. The overstory observed along the ROW does not conform to these requirements and therefore, it is necessary to clear

this vegetation, particularly, the woody roots present. If the ground cover can be spared in this process it should be encouraged, but it is likely most of the ground cover will be removed in this process. This will significantly reduce the level of rehabilitation over the ROW and therefore all repairs to the easement should be completed at this time. After the clearing of vegetation, managing water flow by ensuring there are adequate erosion control berms will be important to protect the repairs and topsoil which has been disturbed and redistributed. If this is managed correctly, it will increase the speed and completeness of further rehabilitation.

Once revegetation has begun, management through regular monitoring and slashing to a minimum height of between 150 mm to 300 mm will be important to keep ground cover healthy while discouraging woody overstory growth. This management will allow ease and effectiveness of aerial and ground surveys and pipeline management in the future.

7.4. Plains Death Adder Habitat

The plains death adder habitat, between KP 355 and K 561, is well rehabilitated although vegetation on the ROW observed was not always representative of vegetation on the ROW. It is strongly recommended that this section of the ROW be protected from any clearing, grading or access by heavy machinery to maintain the cracks and holes. Low level cattle grazing is currently effective at managing the vegetation and therefore it is important that only minor works to control and manage weeds take place in this area.

The following actions are recommended to meet the transitional rehabilitation criteria:

- Limit the clearing of groundcover where possible. Many of the plants that are present are plants that do well in disturbed ground, it will take time for late succession species to reestablish.
- Protect the plains death adder habitat from major works to encourage cracking clay to continue to establish cracks.

This targeted survey pertains only to the land systems surveyed for plains death adder habitat. Additional surveys are required in the future targeting all remaining land systems that intersect with the NGP to meet RMP requirements.

8. REFERENCES

- EcOz. (2020). *Northern Gas Pipeline Transitional Rehabilitation Monitoring Report*. EcOz P/L.
- Jemena. (2022). *NGP Annual Compliance Report*. Jemena Ltd.
- LES. (2021). *Jemena Northern Gas Pipeline Transitional Rehabilitation Assessment*. Low Ecological Services P/L.
- LES. (2023). *Jemena Northern Gas Pipeline Transitional Rehabilitation Assessment*. Low Ecological Services P/L.
- Natural Resources SA. (2015). *Fact Sheet: Bushfire recovery, erosion and water supply*. Government of South Australia. Retrieved from <https://nrmregionsaustralia.com.au/wp-content/uploads/2020/01/bushfire-recovery-soil-erosion.pdf>
- Oliver, I. (2004). Land systems as surrogates for biodiversity in conservation planning. *Ecological Applications*, 485-503.
- Thackway, R., & Cresswell, I. (1995). *An Interim Biogeographic Regionalisation for Australia: a framework for setting priorities in the National Reserves System Cooperative Program Version 4*. Canberra: Australian Nature Conservation Agency.
- Weeds Management Act. (2001). Northern Territory.

9. APPENDICES

Appendix A

The following tables list the GPS points for weeds, land stability issues (erosion, compromised and required berms, subsidence, additional remediation required), vegetation and overgrowth, damaged infrastructure, and plains death adder habitat survey sites.

Detailed information for each site is provided in attached document '2025 Jemena NGP Transitional Rehabilitation Survey Data'.

Weeds

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|--------------|----------|-----------|----------------------------------|----------|-----------|-------------------------------------|
| -19.4577 | 133.9099 | BUFFEL_GRASS | -20.8262 | 139.2901 | KAPOK_BUSH | -20.3635 | 137.3459 | MESQUITE |
| -19.4678 | 134.001 | BUFFEL_GRASS | -20.8266 | 139.2916 | KAPOK_BUSH | -20.3689 | 137.3636 | MESQUITE |
| -19.8915 | 135.9017 | BUFFEL_GRASS | -20.8271 | 139.2939 | KAPOK_BUSH | -20.3635 | 137.3471 | MESQUITE |
| -19.8893 | 135.8952 | BUFFEL_GRASS | -20.8246 | 139.2683 | KAPOK_BUSH | -20.3774 | 137.385 | MESQUITE |
| -19.8892 | 135.8947 | BUFFEL_GRASS | -20.8276 | 139.2964 | KAPOK_BUSH | -20.6356 | 138.1361 | MESQUITE |
| -19.8554 | 135.7926 | BUFFEL_GRASS | -20.8245 | 139.2316 | KAPOK_BUSH | -20.7784 | 139.1763 | MESQUITE |
| -19.8917 | 135.9027 | BUFFEL_GRASS | -20.8277 | 139.2979 | KAPOK_BUSH | -20.7787 | 139.1765 | MESQUITE |
| -19.8903 | 135.8982 | BUFFEL_GRASS | -20.824 | 139.351 | KAPOK_BUSH | -20.3634 | 137.3483 | MESQUITE_NGOORA_B URR |
| -19.8899 | 135.8969 | BUFFEL_GRASS | -20.8169 | 139.3573 | KAPOK_BUSH | -20.6924 | 138.6853 | VAFA |
| -19.8553 | 135.7919 | BUFFEL_GRASS | -20.8109 | 139.3661 | KAPOK_BUSH | -20.6943 | 138.7003 | VAFA |
| -19.8937 | 135.9086 | BUFFEL_GRASS | -20.8121 | 139.4008 | KAPOK_BUSH | -20.3635 | 137.3511 | NGOORA_BURR |
| -19.9007 | 135.9296 | BUFFEL_GRASS | -20.8124 | 139.3869 | KAPOK_BUSH | -20.3634 | 137.3488 | NGOORA_BURR |
| -19.8987 | 135.9232 | BUFFEL_GRASS | -20.8248 | 139.4426 | KAPOK_BUSH | -20.3946 | 137.4278 | NGOORA_BURR |
| -19.8987 | 135.9237 | BUFFEL_GRASS | -20.825 | 139.4585 | KAPOK_BUSH | -20.3635 | 137.3439 | NGOORA_BURR |
| -19.8996 | 135.9264 | BUFFEL_GRASS | -20.8253 | 139.4507 | KAPOK_BUSH | -20.37 | 137.3666 | NGOORA_BURR |
| -19.905 | 135.9428 | BUFFEL_GRASS | -20.8121 | 139.3684 | KAPOK_BUSH | -20.3708 | 137.3662 | NGOORA_BURR |
| -19.9058 | 135.9451 | BUFFEL_GRASS | -20.8125 | 139.3962 | KAPOK_BUSH | -20.3702 | 137.3667 | NGOORA_BURR |
| -19.9083 | 135.9525 | BUFFEL_GRASS | -20.8251 | 139.4469 | KAPOK_BUSH | -20.3702 | 137.3666 | NGOORA_BURR |
| -19.9213 | 135.992 | BUFFEL_GRASS | -20.8344 | 139.3385 | KAPOK_BUSH | -20.3635 | 137.3424 | NGOORA_BURR |
| -19.9227 | 135.9962 | BUFFEL_GRASS | -20.8321 | 139.3418 | KAPOK_BUSH | -20.4631 | 137.593 | NGOORA_BURR |
| -19.8981 | 135.9217 | BUFFEL_GRASS | -20.8291 | 139.3447 | KAPOK_BUSH | -20.4597 | 137.581 | NGOORA_BURR |
| -19.9 | 135.9277 | BUFFEL_GRASS | -20.7335 | 138.931 | KAPOK_MALVASTR UM_NGOORA_VAFA | -20.6374 | 138.1427 | NGOORA_BURR |
| -19.9003 | 135.9286 | BUFFEL_GRASS | -20.327 | 137.2223 | MALVASTRUM | -20.6386 | 138.1473 | NGOORA_BURR |
| -19.9067 | 135.9478 | BUFFEL_GRASS | -20.3331 | 137.2416 | MALVASTRUM | -20.6401 | 138.1525 | NGOORA_BURR |
| -19.9075 | 135.9502 | BUFFEL_GRASS | -20.3634 | 137.3498 | MALVASTRUM | -20.741 | 139.0375 | NGOORA_BURR |
| -19.9096 | 135.9568 | BUFFEL_GRASS | -20.3783 | 137.3873 | MALVASTRUM | -20.7776 | 139.1757 | NGOORA_BURR |
| -19.9144 | 135.9712 | BUFFEL_GRASS | -20.3768 | 137.3834 | MALVASTRUM | -20.718 | 138.8175 | NGOORA_BURR |
| -19.9168 | 135.9783 | BUFFEL_GRASS | -20.3592 | 137.3245 | MALVASTRUM | -20.718 | 138.8175 | NGOORA_BURR |
| -19.9176 | 135.9808 | BUFFEL_GRASS | -20.3932 | 137.4246 | MALVASTRUM | -20.718 | 138.8175 | NGOORA_BURR |
| -19.92 | 135.9879 | BUFFEL_GRASS | -20.3592 | 137.3246 | MALVASTRUM | -20.6458 | 138.1737 | NGOORA_BURR |
| -19.9064 | 135.947 | BUFFEL_GRASS | -20.3654 | 137.3556 | MALVASTRUM | -20.6488 | 138.1879 | NGOORA_BURR |
| -20.8135 | 139.3815 | BUFFEL_GRASS | -20.369 | 137.3638 | MALVASTRUM | -20.6488 | 138.1884 | NGOORA_BURR |
| -20.8123 | 139.402 | BUFFEL_GRASS | -20.3758 | 137.3805 | MALVASTRUM | -20.3188 | 137.1965 | NGOORA_BURR_MALV ASTRUM |
| -19.9324 | 136.0258 | BUFFEL_KAPOK | -20.3841 | 137.4035 | MALVASTRUM | -20.3217 | 137.2056 | NGOORA_BURR_MALV ASTRUM |
| -19.9298 | 136.0179 | BUFFEL_KAPOK | -20.3906 | 137.4184 | MALVASTRUM | -20.3721 | 137.371 | NGOORA_BURR_MALV ASTRUM |
| -19.9315 | 136.0231 | BUFFEL_KAPOK | -20.3946 | 137.4277 | MALVASTRUM | -20.3899 | 137.417 | NGOORA_BURR_MALV ASTRUM |
| -19.9012 | 135.9313 | BUFFEL_KAPOK | -20.4082 | 137.4578 | MALVASTRUM | -20.6381 | 138.1453 | NGOORA_BURR_MALV ASTRUM |
| -19.9025 | 135.9352 | BUFFEL_KAPOK | -20.4182 | 137.4814 | MALVASTRUM | -20.7301 | 138.903 | NGOORA_BURR_MALV ASTRUM |
| -19.903 | 135.9365 | BUFFEL_KAPOK | -20.4214 | 137.489 | MALVASTRUM | -20.7347 | 138.9392 | NGOORA_BURR_MALV ASTRUM |
| -19.933 | 136.0276 | BUFFEL_KAPOK | -20.4214 | 137.489 | MALVASTRUM | -20.3745 | 137.3768 | NGOORA_BURR_MALV ASTRUM_VAFA |
| -19.9123 | 135.9647 | BUFFEL_KAPOK | -20.4128 | 137.4688 | MALVASTRUM | -20.6354 | 138.1352 | NGOORA_BURR_MALV ASTRUM_VAFA |
| -19.9129 | 135.9668 | BUFFEL_KAPOK | -20.3895 | 137.4161 | MALVASTRUM | -20.6368 | 138.1404 | NGOORA_BURR_MALV ASTRUM_VAFA |
| -19.9151 | 135.9734 | BUFFEL_KAPOK | -20.3888 | 137.4144 | MALVASTRUM | -20.6363 | 138.1385 | NGOORA_BURR_MALV ASTRUM_VAFA |
| -20.8116 | 139.373 | BUFFEL_KAPOK | -20.3772 | 137.3844 | MALVASTRUM | -20.6486 | 138.1855 | NGOORA_BURR_PRICK LY_PADDY_MELON |

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|------------------------------------|----------|-----------|------------------------------------|----------|-----------|---------------------|
| -20.8119 | 139.405 | BUFFEL_KAPOK | -20.3606 | 137.3291 | MALVASTRUM | -20.3634 | 137.3493 | PARKINSONIA |
| -20.8125 | 139.3906 | BUFFEL_KAPOK | -20.3681 | 137.3618 | MALVASTRUM | -20.7589 | 139.1234 | PRICKLY_PADDY_MELON |
| -20.8249 | 139.4565 | BUFFEL_KAPOK | -20.3574 | 137.3187 | MALVASTRUM | -19.9227 | 135.9962 | RUBBER_BUSH |
| -20.8105 | 139.4252 | BUFFEL_KAPOK | -20.465 | 137.5991 | MALVASTRUM | -20.42 | 137.4856 | VAFA |
| -20.8116 | 139.4291 | BUFFEL_KAPOK | -20.4855 | 137.6608 | MALVASTRUM | -20.4246 | 137.4966 | VAFA |
| -20.8086 | 139.4209 | BUFFEL_KAPOK | -20.4624 | 137.5908 | MALVASTRUM | -20.425 | 137.4974 | VAFA |
| -20.8119 | 139.411 | BUFFEL_KAPOK | -20.4901 | 137.6712 | MALVASTRUM | -20.4254 | 137.4982 | VAFA |
| -19.4716 | 134.3282 | BUFFEL_GRASS | -20.4894 | 137.6717 | MALVASTRUM | -20.5033 | 137.7009 | VAFA |
| -20.8089 | 139.2044 | CAMEL_BUSH | -20.5013 | 137.6964 | MALVASTRUM | -20.4283 | 137.5052 | VAFA |
| -20.7861 | 139.1814 | CAMEL_BUSH | -20.4944 | 137.6812 | MALVASTRUM | -20.4492 | 137.5543 | VAFA |
| -20.7908 | 139.1846 | CAMEL_BUSH | -20.43 | 137.5076 | MALVASTRUM | -20.496 | 137.6849 | VAFA |
| -20.8245 | 139.2291 | CAMEL_BUSH | -20.4338 | 137.5182 | MALVASTRUM | -20.472 | 137.6203 | VAFA |
| -20.6982 | 138.7268 | CAMEL_BUSH | -20.4282 | 137.504 | MALVASTRUM | -20.4305 | 137.5099 | VAFA |
| -20.698 | 138.7313 | CAMEL_BUSH | -20.4318 | 137.5134 | MALVASTRUM | -20.4462 | 137.5463 | VAFA |
| -20.7549 | 139.1098 | CAMEL_BUSH_PRICKLY_PADDY_MELO N | -20.4608 | 137.5859 | MALVASTRUM | -20.4235 | 137.4939 | VAFA |
| -20.3635 | 137.3447 | FLEABANE_NGOORA_BURR | -20.437 | 137.5257 | MALVASTRUM | -20.6112 | 137.9836 | VAFA |
| -20.812 | 139.3985 | KAPOK_BUSH | -20.4217 | 137.4896 | MALVASTRUM | -20.617 | 138.0095 | VAFA |
| -19.8927 | 135.9054 | KAPOK_BUSH | -20.6256 | 138.069 | MALVASTRUM | -20.6742 | 138.4527 | VAFA |
| -19.9333 | 136.0284 | KAPOK_BUSH | -20.6127 | 137.9889 | MALVASTRUM | -20.6808 | 138.4927 | VAFA |
| -19.9288 | 136.015 | KAPOK_BUSH | -20.6103 | 137.9805 | MALVASTRUM | -20.6823 | 138.5065 | VAFA |
| -19.8987 | 135.9233 | KAPOK_BUSH | -20.622 | 138.0442 | MALVASTRUM | -20.6808 | 138.4955 | VAFA |
| -19.8988 | 135.924 | KAPOK_BUSH | -20.6266 | 138.0746 | MALVASTRUM | -20.6834 | 138.5143 | VAFA |
| -19.8991 | 135.9248 | KAPOK_BUSH | -20.6001 | 137.9465 | MALVASTRUM | -20.7545 | 139.105 | VAFA |
| -19.8997 | 135.9268 | KAPOK_BUSH | -20.6917 | 138.5875 | MALVASTRUM | -20.7269 | 138.8755 | VAFA |
| -19.9005 | 135.9291 | KAPOK_BUSH | -20.692 | 138.6276 | MALVASTRUM | -20.7347 | 138.9437 | VAFA |
| -19.9067 | 135.9477 | KAPOK_BUSH | -20.6914 | 138.5757 | MALVASTRUM | -20.7366 | 138.9618 | VAFA |
| -19.9227 | 135.9962 | KAPOK_BUSH | -20.6894 | 138.5635 | MALVASTRUM | -20.7396 | 139.016 | VAFA |
| -20.1022 | 136.5545 | KAPOK_BUSH | -20.7268 | 138.8747 | MALVASTRUM | -20.7452 | 139.0518 | VAFA |
| -20.8072 | 139.2023 | KAPOK_BUSH | -20.7538 | 139.099 | MALVASTRUM | -20.803 | 139.197 | VAFA |
| -20.7961 | 139.1882 | KAPOK_BUSH | -20.803 | 139.1971 | MALVASTRUM | -20.78 | 139.1773 | VAFA |
| -20.8187 | 139.2169 | KAPOK_BUSH | -20.8055 | 139.1999 | MALVASTRUM | -20.8054 | 139.2 | VAFA |
| -20.8268 | 139.2928 | KAPOK_BUSH | -20.8341 | 139.3394 | MALVASTRUM | -20.8224 | 139.2215 | VAFA |
| -20.8052 | 139.1998 | KAPOK_BUSH | -20.6923 | 138.6853 | MALVASTRUM | -20.824 | 139.2489 | VAFA |
| -20.8036 | 139.1978 | KAPOK_BUSH | -20.6945 | 138.7012 | MALVASTRUM | -20.7659 | 139.1436 | VAFA |
| -20.7549 | 139.1108 | KAPOK_BUSH | -20.6926 | 138.7498 | MALVASTRUM | -20.6921 | 138.6449 | VAFA |
| -20.765 | 139.1421 | KAPOK_BUSH | -20.6979 | 138.7242 | MALVASTRUM | -20.6961 | 138.7124 | VAFA |
| -20.7746 | 139.1718 | KAPOK_BUSH | -20.6922 | 138.6518 | MALVASTRUM | -20.6972 | 138.7195 | VAFA |
| -20.7849 | 139.1806 | KAPOK_BUSH | -20.718 | 138.8175 | MALVASTRUM | -20.6978 | 138.724 | VAFA |
| -20.7934 | 139.1863 | KAPOK_BUSH | -20.6491 | 138.1917 | MALVASTRUM | -20.6982 | 138.7266 | VAFA |
| -20.7938 | 139.1866 | KAPOK_BUSH | -20.648 | 138.1821 | MALVASTRUM | -20.6921 | 138.7524 | VAFA |
| -20.7952 | 139.1875 | KAPOK_BUSH | -20.6502 | 138.2047 | MALVASTRUM | -20.6918 | 138.7535 | VAFA |
| -20.8026 | 139.1965 | KAPOK_BUSH | -20.6504 | 138.2072 | MALVASTRUM | -20.6993 | 138.7787 | VAFA |
| -20.8054 | 139.2 | KAPOK_BUSH | -20.6523 | 138.2307 | MALVASTRUM | -20.7063 | 138.791 | VAFA |
| -20.8099 | 139.2057 | KAPOK_BUSH | -20.6576 | 138.294 | MALVASTRUM | -20.7084 | 138.7958 | VAFA |
| -20.8219 | 139.2208 | KAPOK_BUSH | -20.6478 | 138.1802 | MALVASTRUM_PRICKLY_PADDY_MELO N | -20.709 | 138.7972 | VAFA |
| -20.8246 | 139.2393 | KAPOK_BUSH | -20.4683 | 137.6089 | MALVASTRUM_VAF A | -20.7097 | 138.7988 | VAFA |
| -20.8238 | 139.2587 | KAPOK_BUSH | -20.4443 | 137.5418 | MALVASTRUM_VAF A | -20.7149 | 138.811 | VAFA |
| -20.8238 | 139.2593 | KAPOK_BUSH | -20.4801 | 137.6448 | MALVASTRUM_VAF A | -20.7165 | 138.8148 | VAFA |
| -20.8245 | 139.2678 | KAPOK_BUSH | -20.4483 | 137.5512 | MALVASTRUM_VAF A | -20.721 | 138.8291 | VAFA |
| -20.826 | 139.2795 | KAPOK_BUSH | -20.4697 | 137.6146 | MALVASTRUM_VAF A | -20.6916 | 138.7547 | VAFA |
| -20.8259 | 139.2807 | KAPOK_BUSH | -20.4677 | 137.6074 | MALVASTRUM_VAF A | -20.6921 | 138.6412 | VAFA |
| -20.8261 | 139.2895 | KAPOK_BUSH | -20.6176 | 138.014 | MALVASTRUM_VAF A | -20.6494 | 138.1953 | VAFA |
| -20.8277 | 139.2973 | KAPOK_BUSH | -20.5971 | 137.9377 | MALVASTRUM_VAF A | -20.6493 | 138.1948 | VAFA |

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|------------|----------|-----------|---------------------|----------|-----------|-----------------|
| -20.8299 | 139.3035 | KAPOK_BUSH | -20.623 | 138.0503 | MALVASTRUM_VAF A | -20.6488 | 138.1877 | VAFA |
| -20.8319 | 139.3155 | KAPOK_BUSH | -20.6195 | 138.0276 | MALVASTRUM_VAF A | -20.3797 | 137.3913 | MALVASTRUM_VAFA |
| -20.8288 | 139.2998 | KAPOK_BUSH | -20.6246 | 138.0619 | MALVASTRUM_VAF A | -20.4012 | 137.4421 | MALVASTRUM_VAFA |
| -20.8295 | 139.3008 | KAPOK_BUSH | -20.6698 | 138.4201 | MALVASTRUM_VAF A | -20.3513 | 137.2993 | VERBANE |
| -20.8298 | 139.3021 | KAPOK_BUSH | -20.6919 | 138.6057 | MALVASTRUM_VAF A | | | |
| -20.8281 | 139.2989 | KAPOK_BUSH | -20.7332 | 138.9281 | MALVASTRUM_VAF A | | | |
| -20.8314 | 139.3131 | KAPOK_BUSH | -20.7352 | 138.9493 | MALVASTRUM_VAF A | | | |
| -20.7976 | 139.1902 | KAPOK_BUSH | -20.7269 | 138.8783 | MALVASTRUM_VAF A | | | |
| -20.8063 | 139.2011 | KAPOK_BUSH | -20.7316 | 138.9153 | MALVASTRUM_VAF A | | | |
| -20.7748 | 139.1725 | KAPOK_BUSH | -20.7284 | 138.8892 | MALVASTRUM_VAF A | | | |
| -20.8273 | 139.2948 | KAPOK_BUSH | -19.4591 | 133.9288 | MESQUITE | | | |

Erosion

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|-------------|----------|-----------|-------------|----------|-----------|---------|
| -19.4574 | 133.9068 | ERO_4 | -19.4847 | 134.6625 | SUB_5 | -20.1412 | 136.6662 | ERO_2 |
| -19.4503 | 133.858 | ERO_3 | -19.5151 | 134.7619 | VEHICLE_ERO | -20.1331 | 136.6234 | ERO_2 |
| -19.4537 | 133.88 | ERO_3 | -19.4966 | 134.7058 | VEHICLE_ERO | -20.1772 | 136.7756 | ERO_3 |
| -19.4566 | 133.8988 | ERO_3 | -19.5163 | 134.7655 | VEHICLE_ERO | -20.1355 | 136.6492 | ERO_3 |
| -19.4564 | 133.8961 | ERO_3 | -19.5183 | 134.7715 | VEHICLE_ERO | -20.171 | 136.7562 | ERO_3 |
| -19.4577 | 133.9099 | ERO_4 | -19.4802 | 134.5878 | VEHICLE_ERO | -20.1377 | 136.6559 | ERO_3 |
| -19.4554 | 133.8904 | ERO_4 | -19.5051 | 134.7312 | VEHICLE_ERO | -20.1788 | 136.7799 | ERO_3_4 |
| -19.4574 | 133.9356 | ERO_4 | -19.4846 | 134.6623 | VEHICLE_ERO | -20.1703 | 136.7542 | ERO_4 |
| -19.4575 | 133.9085 | ERO_4 | -19.4905 | 134.6873 | VEHICLE_ERO | -20.1817 | 136.7884 | ERO_4 |
| -19.4583 | 133.9169 | ERO_4 | -19.4843 | 134.6563 | VEHICLE_ERO | -20.1176 | 136.5953 | ERO_4 |
| -19.484 | 134.0814 | ERO_5 | -19.593 | 134.9979 | ERO_3 | -20.175 | 136.7684 | ERO_4 |
| -19.4876 | 134.0931 | ERO_3 | -19.5899 | 134.9885 | ERO_4 | -20.1396 | 136.6614 | ERO_4 |
| -19.4871 | 134.0913 | ERO_3 | -19.5944 | 135.002 | ERO_4 | -20.1772 | 136.775 | ERO_4 |
| -19.4952 | 134.1261 | ERO_3 | -19.5922 | 134.9956 | ERO_4 | -20.1186 | 136.5984 | ERO_4 |
| -19.488 | 134.152 | ERO_3 | -19.5791 | 134.9557 | ERO_5 | -20.1338 | 136.6441 | ERO_4 |
| -19.4732 | 134.3054 | ERO_3 | -19.5863 | 134.9774 | ERO_5 | -20.1342 | 136.6453 | ERO_4 |
| -19.4732 | 134.3065 | ERO_3 | -19.5615 | 134.9024 | ERO_5 | -20.1666 | 136.7429 | ERO_5 |
| -19.4956 | 134.1284 | ERO_3 | -19.5808 | 134.9609 | ERO_5 | -20.1331 | 136.6421 | ERO_5 |
| -19.4866 | 134.0899 | ERO_5 | -19.5808 | 134.9609 | ERO_5 | -20.1515 | 136.6976 | ERO_5 |
| -19.4956 | 134.1318 | ERO_5 | -19.5713 | 134.9322 | ERO_5 | -20.1209 | 136.605 | ERO_5 |
| -19.4827 | 134.205 | ERO_5 | -19.5261 | 134.7952 | VEHICLE_ERO | -20.1242 | 136.6152 | ERO_5 |
| -19.4735 | 134.3012 | ERO_5 | -19.5352 | 134.7956 | VEHICLE_ERO | -20.1364 | 136.6523 | ERO_5 |
| -19.4742 | 134.2915 | ERO_5 | -19.5338 | 134.8188 | VEHICLE_ERO | -20.1245 | 136.6181 | ERO_5 |
| -19.4919 | 134.1079 | SUB_5 | -19.6019 | 135.0248 | ERO_4 | -20.1676 | 136.7513 | ERO_5 |
| -19.4959 | 134.1301 | VEHICLE_ERO | -19.6032 | 135.0288 | ERO_4 | -20.157 | 136.7124 | ERO_5 |
| -19.473 | 134.3085 | VEHICLE_ERO | -19.6043 | 135.032 | ERO_4 | -20.1162 | 136.5907 | ERO_5 |
| -19.4885 | 134.1472 | VEHICLE_ERO | -19.6044 | 135.0324 | ERO_4 | -20.2392 | 136.9619 | ERO_3 |
| -19.4727 | 134.3939 | ERO_3 | -19.6177 | 135.0725 | ERO_4 | -20.2398 | 136.9638 | ERO_3 |
| -19.4712 | 134.3396 | ERO_3 | -19.6141 | 135.0616 | ERO_5 | -20.2404 | 136.9654 | ERO_3 |
| -19.4712 | 134.3365 | ERO_3 | -19.6073 | 135.0409 | VEHICLE_ERO | -20.2232 | 136.9136 | ERO_4 |
| -19.4718 | 134.3278 | ERO_3 | -19.7448 | 135.4576 | ERO_5 | -20.2007 | 136.8459 | ERO_4 |
| -19.4713 | 134.3459 | ERO_3 | -19.6946 | 135.2807 | ERO_5 | -20.2207 | 136.906 | ERO_4 |
| -19.4717 | 134.357 | ERO_3 | -19.7353 | 135.4288 | ERO_5 | -20.2223 | 136.9109 | ERO_4 |
| -19.4718 | 134.3586 | ERO_3 | -19.739 | 135.4359 | ERO_5 | -20.2232 | 136.9138 | ERO_4 |
| -19.4723 | 134.3802 | ERO_3 | -19.6958 | 135.2857 | ERO_3 | -20.2238 | 136.9154 | ERO_4 |
| -19.478 | 134.5522 | ERO_3 | -19.7003 | 135.3071 | ERO_4 | -20.229 | 136.9314 | ERO_4 |
| -19.4726 | 134.3847 | ERO_3 | -19.7438 | 135.4545 | ERO_4 | -20.2377 | 136.9575 | ERO_4 |
| -19.4727 | 134.39 | ERO_3 | -19.732 | 135.4189 | ERO_4 | -20.2397 | 136.9635 | ERO_4 |
| -19.4729 | 134.3966 | ERO_3 | -19.7012 | 135.3112 | ERO_4 | -20.2436 | 136.9752 | ERO_4 |
| -19.4777 | 134.5491 | ERO_3 | -19.6897 | 135.2599 | ERO_5 | -20.2031 | 136.8531 | ERO_4 |
| -19.4722 | 134.3208 | ERO_3 | -19.7331 | 135.4221 | ERO_5 | -20.2059 | 136.8615 | ERO_4 |
| -19.4712 | 134.3433 | ERO_3 | -19.7402 | 135.4435 | ERO_5 | -20.2184 | 136.8994 | ERO_5 |

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|-------------|----------|-----------|---------|----------|-----------|-------------|
| -19.4774 | 134.542 | ERO_3 | -19.7312 | 135.4163 | ERO_5 | -20.2066 | 136.8636 | ERO_5 |
| -19.4713 | 134.3347 | ERO_3 | -19.7006 | 135.3084 | ERO_4_5 | -20.2125 | 136.8813 | ERO_5 |
| -19.4769 | 134.4615 | ERO_3 | -19.7201 | 135.3827 | ERO_5 | -20.2147 | 136.888 | ERO_5 |
| -19.4713 | 134.3331 | ERO_4 | -19.8528 | 135.7846 | ERO_3 | -20.2214 | 136.9084 | ERO_5 |
| -19.4718 | 134.3619 | ERO_4 | -19.8377 | 135.7386 | ERO_5 | -20.2257 | 136.9214 | ERO_5 |
| -19.4714 | 134.3498 | ERO_4 | -19.8395 | 135.7442 | ERO_5 | -20.2657 | 137.0419 | ERO_5 |
| -19.4721 | 134.3216 | ERO_4 | -20.0166 | 136.281 | ERO_2 | -20.3511 | 137.2987 | ERO_3 |
| -19.4711 | 134.3386 | ERO_4 | -20.037 | 136.3428 | ERO_3 | -20.3635 | 137.3511 | ERO_2 |
| -19.4727 | 134.3883 | ERO_4 | -20.0358 | 136.3393 | ERO_3 | -20.3634 | 137.3498 | ERO_3 |
| -19.4739 | 134.428 | ERO_4 | -19.9988 | 136.227 | ERO_4 | -20.401 | 137.4421 | ERO_3 |
| -19.473 | 134.3998 | ERO_4 | -19.9796 | 136.1689 | ERO_4 | -20.3635 | 137.3486 | ERO_3 |
| -19.472 | 134.3229 | ERO_4 | -19.9978 | 136.2236 | ERO_4 | -20.3737 | 137.3747 | ERO_3 |
| -19.4712 | 134.3424 | ERO_4 | -20.0165 | 136.2803 | ERO_4 | -20.393 | 137.4241 | ERO_4 |
| -19.4719 | 134.3655 | ERO_4 | -20.0014 | 136.2349 | ERO_4 | -20.3783 | 137.3873 | ERO_5 |
| -19.477 | 134.4722 | ERO_4 | -19.9911 | 136.2007 | ERO_5 | -20.475 | 137.6292 | ERO_3 |
| -19.4737 | 134.4228 | ERO_4 | -20.0001 | 136.2308 | ERO_5 | -20.6381 | 138.1453 | ERO_3 |
| -19.4716 | 134.329 | ERO_4 | -19.9814 | 136.1738 | ERO_5 | -20.7657 | 139.1445 | ERO_3 |
| -19.4773 | 134.4675 | ERO_4 | -20.0198 | 136.2908 | ERO_5 | -20.7551 | 139.1112 | ERO_4 |
| -19.477 | 134.5132 | ERO_4 | -20.0189 | 136.2875 | ERO_5 | -20.7551 | 139.112 | ERO_5 |
| -19.4712 | 134.3358 | ERO_4 | -20.0204 | 136.2922 | ERO_5 | -20.8124 | 139.3969 | ERO_2 |
| -19.4718 | 134.3256 | ERO_4 | -20.0421 | 136.3582 | ERO_5 | -20.8238 | 139.4369 | ERO_2 |
| -19.4722 | 134.3751 | ERO_5 | -19.9984 | 136.2258 | ERO_5 | -20.8115 | 139.4132 | ERO_3 |
| -19.4724 | 134.381 | ERO_5 | -20.0262 | 136.31 | ERO_5 | -20.8197 | 139.4357 | ERO_3 |
| -19.4735 | 134.4136 | ERO_5 | -20.0192 | 136.2891 | ERO_5 | -20.824 | 139.351 | ERO_3 |
| -19.4732 | 134.4064 | ERO_5 | -20.0439 | 136.3637 | ERO_5 | -20.8278 | 139.3461 | ERO_4 |
| -19.4739 | 134.428 | ERO_5 | -20.0179 | 136.2848 | ERO_5 | -20.8169 | 139.3573 | ERO_4 |
| -19.4759 | 134.4518 | ERO_5 | -20.0979 | 136.5345 | ERO_1 | -20.8236 | 139.4397 | ERO_4 |
| -19.4764 | 134.4561 | ERO_5 | -20.0974 | 136.533 | ERO_1 | -19.764 | 135.5157 | VEHICLE_ERO |
| -19.4769 | 134.4702 | ERO_5 | -20.0993 | 136.5388 | ERO_1 | -19.7517 | 135.4816 | VEHICLE_ERO |
| -19.4769 | 134.4656 | ERO_5 | -20.1002 | 136.5418 | ERO_2 | -20.718 | 138.8175 | ERO_4 |
| -19.4719 | 134.3712 | ERO_5 | -20.116 | 136.5904 | ERO_3 | -20.7207 | 138.8253 | ERO_4 |
| -19.4736 | 134.4182 | ERO_5 | -20.1025 | 136.5494 | ERO_4 | -20.718 | 138.8175 | ERO_4 |
| -19.4733 | 134.4087 | VEHICLE_ERO | -20.1124 | 136.5795 | ERO_4 | | | |
| -19.5055 | 134.7342 | VEHICLE_ERO | -20.0495 | 136.3807 | ERO_5 | | | |
| -19.5032 | 134.7259 | ERO_4 | -20.0439 | 136.3636 | ERO_5 | | | |
| -19.5051 | 134.7313 | ERO_4 | -20.054 | 136.3944 | ERO_5 | | | |
| -19.5094 | 134.7448 | ERO_5 | -20.098 | 136.5345 | ERO_5 | | | |

Compromised and Required Berms

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|--------------|----------|-----------|--------------|----------|-----------|--------------|
| -19.4503 | 133.858 | ADD_BERM | -19.7012 | 135.3112 | ADD_BERM | -20.1703 | 136.7542 | COMP_BERM |
| -19.4537 | 133.88 | SERIES_BERM | -19.7331 | 135.4221 | SERIES_BERMS | -20.1817 | 136.7884 | COMP_BERM |
| -19.4566 | 133.8988 | SERIES_BERM | -19.7312 | 135.4163 | ADD_BERM | -20.1176 | 136.5953 | SERIES_BERMS |
| -19.4564 | 133.8961 | SERIES_BERM | -19.7006 | 135.3084 | SERIES_BERMS | -20.175 | 136.7684 | SERIES_BERMS |
| -19.4554 | 133.8904 | SERIES_BERM | -19.6931 | 135.2743 | ADD_BERM | -20.1186 | 136.5984 | SERIES_BERMS |
| -19.4617 | 133.9642 | ADD_BERM | -19.8437 | 135.757 | SERIES_BERMS | -20.1338 | 136.6441 | SERIES_BERMS |
| -19.4572 | 133.9388 | COMP_BERM | -19.927 | 136.0094 | COMP_BERM | -20.1342 | 136.6453 | SERIES_BERMS |
| -19.4876 | 134.0931 | ADD_BERM | -20.0166 | 136.281 | SERIES_BERMS | -20.1331 | 136.6421 | SERIES_BERMS |
| -19.4871 | 134.0913 | ADD_BERM | -20.037 | 136.3428 | SERIES_BERMS | -20.1245 | 136.6181 | SERIES_BERMS |
| -19.4866 | 134.0899 | ADD_BERM | -20.0358 | 136.3393 | SERIES_BERMS | -20.1162 | 136.5907 | ADD_BERM |
| -19.4735 | 134.3012 | ADD_BERM | -19.9988 | 136.227 | COMP_BERM | -20.1807 | 136.7856 | COMP_BERM |
| -19.4873 | 134.0922 | ADD_BERM | -19.9796 | 136.1689 | SERIES_BERMS | -20.1361 | 136.6506 | COMP_BERM |
| -19.4732 | 134.3055 | ADD_BERM | -19.9978 | 136.2236 | SERIES_BERMS | -20.18 | 136.7831 | COMP_BERM |
| -19.4887 | 134.145 | ADD_BERM | -20.0014 | 136.2349 | ADD_BERM | -20.1701 | 136.7535 | COMP_BERM |
| -19.4749 | 134.2851 | ADD_BERM | -20.0001 | 136.2308 | COMP_BERM | -20.1368 | 136.6533 | COMP_BERM |
| -19.4749 | 134.2851 | ADD_BERM | -19.9814 | 136.1738 | SERIES_BERMS | -20.1793 | 136.7808 | COMP_BERM |
| -19.4713 | 134.3459 | SERIES_BERMS | -20.0198 | 136.2908 | SERIES_BERMS | -20.179 | 136.7804 | COMP_BERM |
| -19.4717 | 134.357 | SERIES_BERMS | -20.0189 | 136.2875 | SERIES_BERMS | -20.1786 | 136.7794 | COMP_BERM |
| -19.4723 | 134.3802 | ADD_BERM | -20.0204 | 136.2922 | SERIES_BERMS | -20.122 | 136.6086 | SERIES_BERMS |
| -19.478 | 134.5522 | ADD_BERM | -20.0421 | 136.3582 | SERIES_BERMS | -20.2232 | 136.9136 | COMP_BERM |
| -19.4714 | 134.3498 | SERIES_BERMS | -19.9984 | 136.2258 | SERIES_BERMS | -20.2184 | 136.8994 | COMP_BERM |
| -19.477 | 134.4722 | SERIES_BERMS | -20.0262 | 136.31 | SERIES_BERMS | -20.2498 | 136.9934 | COMP_BERM |
| -19.477 | 134.5132 | SERIES_BERMS | -20.0192 | 136.2891 | SERIES_BERMS | -20.2596 | 137.0236 | COMP_BERM |

| | | | | | | | | |
|----------|----------|--------------|----------|----------|--------------|----------|----------|--------------|
| -19.4716 | 134.329 | SERIES_BERMS | -20.0439 | 136.3637 | COMP_BERM | -20.2207 | 136.9063 | COMP_BERM |
| -19.5899 | 134.9885 | SERIES_BERMS | -20.0179 | 136.2848 | SERIES_BERMS | -20.2597 | 137.0239 | COMP_BERM |
| -19.5922 | 134.9956 | SERIES_BERMS | -20.0292 | 136.3194 | SERIES_BERMS | -20.2523 | 137.0014 | COMP_BERM |
| -19.5791 | 134.9557 | SERIES_BERMS | -20.0368 | 136.3423 | COMP_BERM | -20.1939 | 136.8252 | SERIES_BERMS |
| -19.5863 | 134.9774 | SERIES_BERMS | -20.0304 | 136.3229 | COMP_BERM | -20.2657 | 137.0419 | SERIES_BERMS |
| -19.5615 | 134.9024 | SERIES_BERMS | -20.0168 | 136.2816 | COMP_BERM | -20.475 | 137.6292 | SERIES_BERMS |
| -19.5808 | 134.9609 | SERIES_BERMS | -20.0164 | 136.2804 | COMP_BERM | -20.4631 | 137.593 | COMP_BERM |
| -19.5808 | 134.9609 | SERIES_BERMS | -20.0434 | 136.3619 | COMP_BERM | -20.4624 | 137.5908 | COMP_BERM |
| -19.5713 | 134.9322 | SERIES_BERMS | -20.0384 | 136.347 | ADD_BERM | -20.5013 | 137.6964 | SERIES_BERMS |
| -19.5747 | 134.9423 | SERIES_BERMS | -20.0979 | 136.5345 | ADD_BERM | -20.4944 | 137.6812 | SERIES_BERMS |
| -19.5844 | 134.9718 | SERIES_BERMS | -20.0495 | 136.3807 | COMP_BERM | -20.4797 | 137.6432 | SERIES_BERMS |
| -19.6177 | 135.0725 | ADD_BERM | -20.0439 | 136.3636 | COMP_BERM | -20.6255 | 138.0682 | COMP_BERM |
| -19.6177 | 135.0725 | ADD_BERM | -20.054 | 136.3944 | COMP_BERM | -20.6797 | 138.4869 | COMP_BERM |
| -19.6141 | 135.0616 | SERIES_BERMS | -20.0523 | 136.3891 | COMP_BERM | -20.7782 | 139.1761 | ADD_BERM |
| -19.7353 | 135.4288 | SERIES_BERMS | -20.1772 | 136.7756 | COMP_BERM | -20.8115 | 139.4132 | COMP_BERM |
| -19.6958 | 135.2857 | ADD_BERM | -20.1355 | 136.6492 | COMP_BERM | -20.8197 | 139.4357 | COMP_BERM |
| -19.732 | 135.4189 | SERIES_BERMS | -20.1377 | 136.6559 | COMP_BERM | -20.8121 | 139.4008 | COMP_BERM |
| | | | | | | -20.7207 | 138.8251 | COMP_BERM |

Subsidence

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|-------|----------|-----------|--------------|----------|-----------|-------|
| -19.4574 | 133.9068 | SUB_4 | -19.4857 | 134.087 | SUB_5 | -20.4231 | 137.4929 | SUB_4 |
| -19.4637 | 133.9746 | SUB_4 | -19.4586 | 133.9206 | SUB_5 | -20.4242 | 137.4953 | SUB_4 |
| -19.4589 | 133.9291 | SUB_4 | -19.5055 | 134.7342 | SUB_VEHICHLE | -20.4828 | 137.6525 | SUB_4 |
| -19.4833 | 134.0789 | SUB_4 | -20.0563 | 136.4019 | SUB_5 | -20.7675 | 139.1501 | SUB_4 |
| -19.457 | 133.9031 | SUB_5 | -20.3795 | 137.3905 | SUB_5 | -20.706 | 138.7903 | SUB_4 |
| -19.4847 | 134.0836 | SUB_5 | -20.3511 | 137.2987 | SUB_CATTLE | | | |

Land Stability Remediation

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|--------------------|----------|-----------|--------------------|----------|-----------|---|
| -19.4503 | 133.858 | BRING_IN_WIN DROWS | -19.5899 | 134.9885 | BRING_IN_WIN DROWS | -20.117 | 136.5934 | BRING_IN_WI NDROWS |
| -19.4713 | 134.3459 | LEVEL | -19.5922 | 134.9956 | BRING_IN_WIN DROWS | -20.1186 | 136.5984 | BRING_IN_WI NDROWS |
| -19.4713 | 134.3331 | BRING_IN_WIN DROWS | -19.5968 | 135.0096 | REPLACE_TOP SOIL | -20.1242 | 136.6152 | BRING_IN_WI NDROWS |
| -19.4717 | 134.357 | LEVEL | -19.602 | 135.0248 | BRING_IN_WIN DROWS | -20.1242 | 136.6152 | REPLACE_TOP SOIL_REDISTRIBUTE_VEG_PILES |
| -19.4723 | 134.3802 | REPLACE_TOP SOIL | -19.6035 | 135.0296 | BRING_IN_WIN DROWS | -20.1274 | 136.6247 | BRING_IN_WI NDROWS |
| -19.4724 | 134.381 | BRING_IN_WIN DROWS | -19.6043 | 135.032 | LEVEL | -20.1303 | 136.6336 | BRING_IN_WI NDROWS |
| -19.4727 | 134.3832 | BRING_IN_WIN DROWS | -19.6141 | 135.0616 | BRING_IN_WIN DROWS | -20.1331 | 136.6421 | BRING_IN_WI NDROWS |
| -19.473 | 134.3085 | LEVEL | -19.6157 | 135.0666 | BRING_IN_WIN DROWS | -20.1338 | 136.6441 | BRING_IN_WI NDROWS |
| -19.4732 | 134.3065 | BRING_IN_WIN DROWS | -19.6207 | 135.0815 | BRING_IN_WIN DROWS | -20.1342 | 136.6453 | BRING_IN_WI NDROWS |
| -19.4733 | 134.4087 | LEVEL | -19.6221 | 135.086 | BRING_IN_WIN DROWS | -20.1364 | 136.6523 | BRING_IN_WI NDROWS |
| -19.4739 | 134.428 | BRING_IN_WIN DROWS | -19.6266 | 135.0997 | BRING_IN_WIN DROWS | -20.1433 | 136.6729 | REPLACE_TOP SOIL |
| -19.4739 | 134.428 | LEVEL | -19.637 | 135.131 | BRING_IN_WIN DROWS | -20.1451 | 136.6783 | REPLACE_TOP SOIL |
| -19.4742 | 134.2915 | LEVEL | -19.6832 | 135.2354 | BRING_IN_WIN DROWS | -20.1487 | 136.6891 | REPLACE_TOP SOIL_REDISTRIBUTE_VEG_PILES |
| -19.4769 | 134.4656 | BRING_IN_WIN DROWS | -19.6931 | 135.2743 | REPLACE_TOP SOIL | -20.1493 | 136.691 | BRING_IN_WI NDROWS |
| -19.477 | 134.4722 | BRING_IN_WIN DROWS | -19.6946 | 135.2807 | REPLACE_TOP SOIL | -20.4231 | 137.4929 | REPLACE_TOP SOIL |
| -19.477 | 134.4722 | LEVEL | -19.7106 | 135.354 | BRING_IN_WIN DROWS | -20.6157 | 138.0007 | BRING_IN_WI NDROWS |

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|----------------------------|----------|-----------|---|----------|-----------|-----------------------|
| -19.4774 | 134.0599 | BRING_IN_WIN DROWS | -19.7163 | 135.3712 | BRING_IN_WIN DROWS | -20.617 | 138.0095 | BRING_IN_WI NDROWS |
| -19.4827 | 134.205 | REPLACE_TOP SOIL | -19.8348 | 135.7299 | LEVEL | -20.6195 | 138.0276 | BRING_IN_WI NDROWS |
| -19.4843 | 134.6563 | LEVEL | -19.8395 | 135.7442 | BRING_IN_WIN DROWS | -20.6211 | 138.0376 | BRING_IN_WI NDROWS |
| -19.4846 | 134.6623 | LEVEL | -19.8437 | 135.757 | BRING_IN_WIN DROWS | -20.6409 | 138.1553 | BRING_IN_WI NDROWS |
| -19.488 | 134.152 | FILL | -20.0013 | 136.2335 | REPLACE_TOP SOIL_REDISTR BUTE_VEG_PIL ES | -20.6438 | 138.1665 | BRING_IN_WI NDROWS |
| -19.4905 | 134.6873 | LEVEL | -20.0109 | 136.2638 | REPLACE_TOP SOIL | -20.6523 | 138.2307 | BRING_IN_WI NDROWS |
| -19.5051 | 134.7312 | LEVEL | -20.0204 | 136.2922 | REPLACE_TOP SOIL_REDISTR BUTE_VEG_PIL ES | -20.668 | 138.4076 | BRING_IN_WI NDROWS |
| -19.5055 | 134.7342 | LEVEL | -20.023 | 136.3004 | REPLACE_TOP SOIL | -20.6689 | 138.4141 | BRING_IN_WI NDROWS |
| -19.5267 | 134.7986 | BRING_IN_WIN DROWS | -20.0421 | 136.3582 | REPLACE_TOP SOIL_REDISTR BUTE_VEG_PIL ES | -20.6704 | 138.425 | BRING_IN_WI NDROWS |
| -19.5341 | 134.8196 | BRING_IN_WIN DROWS | -20.0439 | 136.3637 | REPLACE_TOP SOIL_REDISTR BUTE_VEG_PIL ES | -20.6796 | 138.4872 | BRING_IN_WI NDROWS |
| -19.5352 | 134.7956 | BRING_IN_WIN DROWS | -20.0563 | 136.4019 | BRING_IN_WIN DROWS | -20.6823 | 138.5052 | REPLACE_TOP SOIL |
| -19.5424 | 134.8426 | BRING_IN_WIN DROWS | -20.0711 | 136.449 | BRING_IN_WIN DROWS | -20.7657 | 139.1445 | REPLACE_TOP SOIL |
| -19.5489 | 134.8644 | BRING_IN_WIN DROWS | -20.097 | 136.5316 | BRING_IN_WIN DROWS | | | |
| -19.5489 | 134.8644 | REDISTRIBUTE _VEG_PILES | -20.1002 | 136.5418 | BRING_IN_WIN DROWS | | | |
| -19.5529 | 134.8765 | BRING_IN_WIN DROWS | -20.1025 | 136.5494 | BRING_IN_WIN DROWS | | | |
| -19.5674 | 134.9202 | BRING_IN_WIN DROWS | -20.116 | 136.5904 | BRING_IN_WIN DROWS | | | |
| -19.5808 | 134.9609 | REDISTRIBUTE _VEG_PILES | -20.1162 | 136.5907 | BRING_IN_WIN DROWS | | | |
| -19.5844 | 134.9718 | REPLACE_TOP SOIL | -20.1162 | 136.5907 | REPLACE_TOP SOIL_REDISTR BUTE_VEG_PIL ES | | | |

Vegetation and Overgrowth

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|------------|----------|-----------|------------|----------|-----------|-------|
| -20.8358 | 139.3345 | VEG_2 | -20.1631 | 136.7325 | VEG_5 | -19.7088 | 135.3482 | VEG_2 |
| -20.833 | 139.3206 | VEG_4 | -20.158 | 136.717 | OVERGROWTH | -19.706 | 135.3345 | VEG_3 |
| -20.833 | 139.3206 | OVERGROWTH | -20.1554 | 136.7093 | VEG_5 | -19.7029 | 135.3195 | VEG_4 |
| -20.8253 | 139.4507 | VEG_3 | -20.1515 | 136.6976 | VEG_5 | -19.7012 | 135.3112 | VEG_3 |
| -20.8238 | 139.4369 | VEG_5 | -20.1505 | 136.6943 | VEG_5 | -19.7006 | 135.3084 | VEG_2 |
| -20.8116 | 139.4291 | OVERGROWTH | -20.1493 | 136.691 | VEG_4 | -19.6958 | 135.2857 | VEG_4 |
| -20.8105 | 139.4252 | OVERGROWTH | -20.1487 | 136.6891 | VEG_1 | -19.6946 | 135.2807 | VEG_2 |
| -20.7543 | 139.1025 | VEG_5 | -20.1462 | 136.6813 | VEG_2 | -19.6939 | 135.2777 | VEG_2 |
| -20.7538 | 139.099 | VEG_5 | -20.1451 | 136.6783 | VEG_3 | -19.687 | 135.2485 | VEG_4 |
| -20.7392 | 139.0009 | VEG_5 | -20.1433 | 136.6729 | VEG_2 | -19.6855 | 135.2426 | VEG_3 |
| -20.737 | 138.9711 | VEG_5 | -20.1412 | 136.6662 | VEG_4 | -19.6832 | 135.2354 | VEG_4 |
| -20.7347 | 138.9437 | VEG_5 | -20.1377 | 136.6559 | VEG_5 | -19.6807 | 135.2275 | VEG_4 |
| -20.7316 | 138.9153 | VEG_5 | -20.1364 | 136.6523 | VEG_3 | -19.676 | 135.2127 | VEG_5 |
| -20.7284 | 138.8892 | VEG_5 | -20.1303 | 136.6336 | VEG_5 | -19.6735 | 135.208 | VEG_4 |
| -20.7269 | 138.8721 | VEG_5 | -20.1285 | 136.628 | VEG_5 | -19.6694 | 135.1999 | VEG_4 |
| -20.6979 | 138.7326 | VEG_5 | -20.1274 | 136.6247 | VEG_4 | -19.6671 | 135.1953 | VEG_5 |
| -20.6925 | 138.7505 | VEG_5 | -20.1237 | 136.6135 | VEG_4 | -19.6632 | 135.1874 | VEG_4 |
| -20.6923 | 138.6854 | VEG_5 | -20.122 | 136.6086 | VEG_2 | -19.6606 | 135.1824 | VEG_3 |
| -20.6921 | 138.6467 | VEG_5 | -20.1209 | 136.605 | VEG_2 | -19.6392 | 135.1376 | VEG_3 |
| -20.6921 | 138.6412 | VEG_4 | -20.1204 | 136.6036 | VEG_5 | -19.6314 | 135.1142 | VEG_3 |

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|--------------|----------|-----------|--------------|----------|-----------|------------|
| -20.692 | 138.629 | VEG_3 | -20.1176 | 136.5953 | VEG_4 | -19.6242 | 135.0921 | VEG_2 |
| -20.686 | 138.534 | VEG_1 | -20.117 | 136.5934 | VEG_5 | -19.6141 | 135.0616 | VEG_3 |
| -20.686 | 138.534 | TREE_ON_PIPE | -20.1162 | 136.5907 | VEG_1 | -19.6141 | 135.0616 | VEG_3 |
| -20.6839 | 138.5176 | VEG_1 | -20.1105 | 136.5739 | VEG_5 | -19.6073 | 135.0409 | VEG_3 |
| -20.6834 | 138.5143 | OVERGROWTH | -20.0984 | 136.536 | VEG_1 | -19.6047 | 135.0331 | VEG_4 |
| -20.6823 | 138.5052 | VEG_2 | -20.097 | 136.5316 | VEG_5 | -19.6033 | 135.0288 | VEG_3 |
| -20.6818 | 138.502 | VEG_5 | -20.0563 | 136.4019 | OVERGROWTH | -19.5984 | 135.0139 | VEG_3 |
| -20.6808 | 138.4955 | VEG_5 | -20.0495 | 136.3807 | VEG_5 | -19.5976 | 135.0117 | VEG_4 |
| -20.6796 | 138.4872 | VEG_5 | -20.0439 | 136.3637 | VEG_4 | -19.5968 | 135.0096 | VEG_2 |
| -20.6731 | 138.4435 | VEG_5 | -20.0439 | 136.3637 | VEG_4 | -19.593 | 134.9979 | VEG_4 |
| -20.6689 | 138.4141 | VEG_5 | -20.0358 | 136.3393 | VEG_5 | -19.593 | 134.9979 | OVERGROWTH |
| -20.6689 | 138.4141 | OVERGROWTH | -20.0292 | 136.3194 | VEG_2 | -19.5844 | 134.9718 | VEG_2 |
| -20.6674 | 138.4026 | VEG_5 | -20.0204 | 136.2922 | VEG_2 | -19.5791 | 134.9557 | VEG_4 |
| -20.6538 | 138.2487 | VEG_5 | -20.0192 | 136.2891 | VEG_5 | -19.5747 | 134.9423 | VEG_4 |
| -20.6435 | 138.1652 | VEG_4 | -20.0192 | 136.2891 | OVERGROWTH | -19.5674 | 134.9202 | VEG_4 |
| -20.6386 | 138.1473 | VEG_5 | -20.0165 | 136.2803 | VEG_5 | -19.5569 | 134.8886 | VEG_4 |
| -20.6266 | 138.0746 | VEG_5 | -20.0109 | 136.2638 | VEG_3 | -19.5529 | 134.8765 | VEG_4 |
| -20.623 | 138.0503 | VEG_5 | -20.0014 | 136.2349 | VEG_5 | -19.5489 | 134.8644 | VEG_3 |
| -20.6195 | 138.0276 | VEG_5 | -19.9994 | 136.2288 | VEG_5 | -19.5478 | 134.8609 | VEG_4 |
| -20.617 | 138.0095 | VEG_5 | -19.9994 | 136.2288 | OVERGROWTH | -19.5364 | 134.8264 | OVERGROWTH |
| -20.6072 | 137.9706 | WHITEWOOD | -19.9953 | 136.2152 | VEG_5 | -19.5361 | 134.8255 | VEG_4 |
| -20.6001 | 137.9465 | VEG_5 | -19.9903 | 136.1989 | VEG_5 | -19.5361 | 134.8255 | OVERGROWTH |
| -20.5944 | 137.9311 | VEG_5 | -19.9903 | 136.1989 | OVERGROWTH | -19.5352 | 134.7956 | VEG_2 |
| -20.5013 | 137.6964 | VEG_5 | -19.9697 | 136.1386 | VEG_5 | -19.5338 | 134.8188 | VEG_3 |
| -20.4975 | 137.6882 | VEG_5 | -19.9697 | 136.1386 | OVERGROWTH | -19.5261 | 134.7952 | VEG_3 |
| -20.4855 | 137.6608 | VEG_5 | -19.9697 | 136.1387 | VEG_5 | -19.498 | 134.7101 | VEG_4 |
| -20.4807 | 137.6462 | VEG_4 | -19.9453 | 136.0765 | VEG_5 | -19.4956 | 134.1318 | VEG_2 |
| -20.465 | 137.5991 | VEG_5 | -19.9396 | 136.0474 | OVERGROWTH | -19.4888 | 134.0968 | VEG_2 |
| -20.4624 | 137.5908 | VEG_5 | -19.9277 | 136.0115 | OVERGROWTH | -19.4847 | 134.0836 | VEG_2 |
| -20.4483 | 137.5512 | VEG_5 | -19.927 | 136.0094 | OVERGROWTH | -19.4845 | 134.6585 | VEG_5 |
| -20.4443 | 137.5418 | VEG_5 | -19.912 | 135.964 | VEG_5 | -19.4844 | 134.6576 | OVERGROWTH |
| -20.4256 | 137.4988 | VEG_5 | -19.912 | 135.964 | OVERGROWTH | -19.4843 | 134.6561 | VEG_4 |
| -20.4256 | 137.4988 | OVERGROWTH | -19.9106 | 135.9597 | VEG_5 | -19.4842 | 134.1906 | VEG_2 |
| -20.4235 | 137.4939 | VEG_5 | -19.9106 | 135.9597 | OVERGROWTH | -19.484 | 134.0814 | VEG_3 |
| -20.4217 | 137.4896 | VEG_5 | -19.9084 | 135.9532 | VEG_5 | -19.4811 | 134.6035 | VEG_4 |
| -20.391 | 137.4193 | VEG_5 | -19.9 | 135.9276 | VEG_5 | -19.4802 | 134.5878 | VEG_4 |
| -20.3666 | 137.3578 | VEG_5 | -19.8981 | 135.9217 | OVERGROWTH | -19.4791 | 134.5708 | VEG_4 |
| -20.3635 | 137.3487 | VEG_5 | -19.8957 | 135.9145 | VEG_5 | -19.478 | 134.5565 | VEG_1 |
| -20.3471 | 137.2855 | VEG_5 | -19.8957 | 135.9145 | OVERGROWTH | -19.478 | 134.5522 | VEG_1 |
| -20.3389 | 137.2594 | VEG_5 | -19.8954 | 135.9136 | VEG_5 | -19.4776 | 134.2568 | VEG_2 |
| -20.327 | 137.2223 | VEG_5 | -19.8899 | 135.8969 | VEG_5 | -19.4774 | 134.542 | VEG_2 |
| -20.3239 | 137.2127 | VEG_3 | -19.8899 | 135.8969 | OVERGROWTH | -19.477 | 134.5132 | VEG_2 |
| -20.3125 | 137.1775 | VEG_5 | -19.8882 | 135.8919 | VEG_5 | -19.4769 | 134.4816 | VEG_1 |
| -20.2974 | 137.1343 | VEG_3 | -19.8882 | 135.8919 | OVERGROWTH | -19.4769 | 134.5274 | VEG_2 |
| -20.2865 | 137.1047 | VEG_5 | -19.8576 | 135.7991 | VEG_5 | -19.4769 | 134.4899 | VEG_2 |
| -20.2825 | 137.0925 | VEG_5 | -19.8576 | 135.7991 | OVERGROWTH | -19.4769 | 134.4702 | VEG_2 |
| -20.2802 | 137.0857 | VEG_4 | -19.8559 | 135.7938 | VEG_5 | -19.4764 | 134.4561 | VEG_4 |
| -20.2774 | 137.077 | VEG_4 | -19.8559 | 135.7938 | TREE_ON_PIPE | -19.4759 | 134.4518 | VEG_3 |
| -20.2735 | 137.0674 | VEG_4 | -19.8544 | 135.7893 | VEG_4 | -19.4757 | 134.2764 | VEG_3 |
| -20.2657 | 137.0419 | VEG_5 | -19.8528 | 135.7846 | VEG_3 | -19.4746 | 134.2876 | VEG_4 |
| -20.2498 | 136.9934 | OVERGROWTH | -19.8437 | 135.757 | VEG_3 | -19.4744 | 134.4395 | VEG_3 |
| -20.2398 | 136.9638 | VEG_5 | -19.8395 | 135.7442 | VEG_3 | -19.4742 | 134.0497 | VEG_2 |
| -20.2392 | 136.9619 | VEG_5 | -19.8305 | 135.717 | VEG_2 | -19.4732 | 134.3054 | VEG_3 |
| -20.2392 | 136.9619 | OVERGROWTH | -19.8267 | 135.7055 | VEG_2 | -19.4726 | 134.3847 | VEG_2 |
| -20.2327 | 136.9424 | VEG_5 | -19.8234 | 135.6954 | VEG_3 | -19.4723 | 134.3186 | VEG_5 |
| -20.229 | 136.9314 | VEG_5 | -19.8213 | 135.689 | VEG_2 | -19.4722 | 134.3208 | VEG_3 |
| -20.2231 | 136.9136 | VEG_5 | -19.8189 | 135.6818 | VEG_3 | -19.4716 | 134.329 | VEG_3 |
| -20.2223 | 136.9109 | OVERGROWTH | -19.799 | 135.6214 | VEG_4 | -19.4712 | 134.3424 | VEG_3 |
| -20.2214 | 136.9084 | VEG_5 | -19.7858 | 135.5815 | VEG_3 | -19.4613 | 133.9624 | VEG_1 |
| -20.2207 | 136.9063 | VEG_5 | -19.7663 | 135.5226 | VEG_4 | -19.4591 | 133.9269 | VEG_1 |
| -20.2207 | 136.9063 | OVERGROWTH | -19.763 | 135.5127 | VEG_3 | -19.4586 | 133.9206 | VEG_1 |
| -20.2207 | 136.906 | VEG_5 | -19.755 | 135.4889 | VEG_4 | -19.4578 | 133.9441 | VEG_1 |
| -20.2184 | 136.8994 | OVERGROWTH | -19.7475 | 135.4657 | VEG_3 | -19.4576 | 133.9341 | VEG_1 |
| -20.2125 | 136.8813 | VEG_5 | -19.7456 | 135.46 | VEG_4 | -19.4574 | 133.9421 | VEG_1 |
| -20.2088 | 136.8703 | VEG_5 | -19.7448 | 135.4576 | VEG_3 | -19.4572 | 133.9388 | VEG_1 |
| -20.2088 | 136.8703 | OVERGROWTH | -19.7402 | 135.4435 | VEG_3 | -19.457 | 133.9031 | VEG_2 |
| -20.2059 | 136.8615 | VEG_5 | -19.739 | 135.4359 | VEG_3 | -19.4564 | 133.8961 | VEG_2 |
| -20.2059 | 136.8615 | OVERGROWTH | -19.732 | 135.4189 | VEG_4 | -19.456 | 133.894 | VEG_4 |

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|------------|----------|-----------|-------|----------|-----------|-------|
| -20.1989 | 136.8403 | OVERGROWTH | -19.7298 | 135.4119 | VEG_3 | -19.4537 | 133.88 | VEG_2 |
| -20.1907 | 136.8158 | VEG_5 | -19.7289 | 135.4093 | VEG_2 | | | |
| -20.1907 | 136.8158 | OVERGROWTH | -19.7271 | 135.3874 | VEG_3 | | | |
| -20.1877 | 136.8066 | OVERGROWTH | -19.7255 | 135.3989 | VEG_3 | | | |
| -20.1868 | 136.8034 | VEG_5 | -19.7163 | 135.3712 | VEG_3 | | | |
| -20.175 | 136.7684 | OVERGROWTH | -19.7126 | 135.3598 | VEG_2 | | | |

Infrastructure

| Latitude | Longitude | Code | Latitude | Longitude | Code | Latitude | Longitude | Code |
|----------|-----------|--------------|----------|-----------|----------------------------|----------|-----------|-----------------------|
| -19.466 | 133.9872 | SIGN_NOT_VIS | -20.327 | 137.2223 | DAMAGED_POLE_EXPOSED_WIRES | -20.6782 | 138.4791 | DAMAGED_SIGN |
| -19.5713 | 134.9322 | DAMAGED_SIGN | -20.3592 | 137.3245 | DAMAGED_SIGN | -20.8109 | 139.3661 | BURNED_SIGN |
| -20.3298 | 137.2313 | DAMAGED_SIGN | -20.3861 | 137.4081 | DAMAGED_SIGN | -20.8332 | 139.3217 | BURNED_SIGNS_MULTIPLE |
| -20.3285 | 137.2268 | DAMAGED_SIGN | -20.3961 | 137.4312 | DAMAGED_SIGN | -20.8355 | 139.3377 | BURNED_SIGNS_MULTIPLE |
| -20.3389 | 137.2594 | DAMAGED_SIGN | -20.4022 | 137.4446 | DAMAGED_POLE_EXPOSED_WIRES | | | |
| -20.341 | 137.2669 | DAMAGED_SIGN | -20.465 | 137.5991 | DAMAGED_SIGN | | | |
| -20.3204 | 137.2015 | DAMAGED_SIGN | -20.6791 | 138.4845 | DAMAGED_SIGN | | | |

Plains Death Adder Habitat Survey Sites

| Latitude | Longitude | Site | Latitude | Longitude | Site | Latitude | Longitude | Site |
|----------|-----------|------|----------|-----------|-------|----------|-----------|------|
| -20.3058 | 137.1572 | MG01 | -20.5476 | 137.8091 | MG06* | -20.6917 | 138.5753 | MG11 |
| -20.3352 | 137.2484 | MG02 | -20.6155 | 138.0008 | MG07 | -20.6155 | 138.0008 | MG12 |
| -20.3706 | 137.3675 | MG03 | -20.6508 | 138.2119 | MG08 | -20.692 | 138.629 | MG13 |
| -20.4461 | 137.547 | MG04 | -20.6530 | 138.2397 | MG09 | -20.7217 | 138.8377 | MG14 |
| -20.4899 | 137.6713 | MG05 | -20.6587 | 138.3077 | MG10 | | | |

* Location for site MG06 is approximate only

2.2 APPENDIX B – NOTIFICATION OF COMMENCEMENT

Marc Rullo

From: Marc Rullo
Sent: Monday, 29 May 2017 3:12 PM
To: EPBCMonitoring@environment.gov.au
Cc: Russell Brooks; Jeff.richardson@ecoz.com.au; Cox, Vaughn
Subject: Notification of Commencement | Jemena Northern Gas Pipeline (EPBC 2015/7569)

Dear Sir or Madam,

In accordance with Condition 7 of EPBC Decision 2015/7569 (Jemena Northern Gas Pipeline), Please be advised the commencement of actions was **20 May 2017**.

Please acknowledge receipt of this email. If you require further information, do not hesitate to contact me using the details below.

Thank you and kind regards,

Marc Rullo
Project Engineer – Northern Gas Pipeline
Jemena
Level 15, 567 Collins Street, Melbourne, VIC 3000
T: (03) 9173 7810 | M: 0400 375 012 | F: (03) 9173 7515
marc.rullo@jemena.com.au | www.jemena.com.au

